Approved CR

IAA Honolulu
91-445A Komohana St
Branch No 114
Kapolei, HI 96707
(808) 682-2858/(808) 682-3988
WHOLESALE ASSESSMENT ONLY

| | |
|---|---|
| Make/Model: | **2018 FORD TRANSIT-350** |
| Bodystyle/Series: | **Wagon XL** |
| Color: | **White** |
| Mileage: | **51,700 (Verified)** |
| Turn-in Mileage: | - |
| VIN: | **1FBZX2ZM1JKB43084** |
| Work Order/ Stock Number: | **46535904** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | **G433455V** |
| Vehicle Grade : | **Grade 3.3** |
| Remarks: | - |
| Announcements: | - |
| Certification : | - |
| Req. Prev. Repair Order: | - |




Drivable: Yes

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Automatic Transmission** | A/C: | **No** |
| Engine: | **6-Cylinder Gas** | Cruise Control: | **Yes** |
| Engine Size: | **3.7 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **Yes** |
| Radio: | - | Pwr Windows | **Yes** |
| Interior - Type/Color: | **Vinyl Interior /GRAY** | Rear Defroster: | **Yes** |
| Airbag: | **Driver Side Air Bag** | Tilt Steering: | **Yes** |
| Seats: | **Memory** | Drive Type: | **Rear Wheel Drive** |
| Seat Count: | - | Brakes: | **Hydraulic Brakes** |

## Equipment

Additional Equipment:

| | | |
|---|---|---|
| Car Tire Size - LF 235 / 65 R 16 | Car Tire Size - LR 235 / 65 R 16 | Car Tire Size - RR 235 / 65 R 16 |
| Car Tire Size - RF 235 / 65 R 16 | LF Tires - 10/32 inch | LR Tires - 11/32 inch |
| RF Tires - 10/32 inch | RR Tires - 11/32 inch | Tire Brand - Front Left - TOYO |
| Tire Brand - Front Right - TOYO | Tire Brand - Rear Left - TOYO | Tire Brand - Rear Right - TOYO |
| Tire Model - RR - Open Country H/T Ii | Tire Model - RF - Open Country H/T Ii | Tire Model - LR - Open Country H/T Ii |
| Tire Model - LF - Open Country H/T Ii | | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Rear Seats | Photo Only | - | - |
|  | Left Front Fender | Photo Only | - | - |
|  | Left Rear Bumper/Cover | Photo Only | - | - |
|  | Right Rear Bumper/Cover | Photo Only | - | - |
|  | Photo - Dash | Photo Only | - | - |
|  | Extra Photo 1 | Photo Only | - | - |
|  | Odometer | Photo Only | - | - |
|  | Right Front Fender | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Extra Photo 3 | Photo Only | - | - |
|  | Extra Photo 2 | Photo Only | - | - |
|  | Rear Bumper | Photo Only | - | - |
|  | Instrument Panel | Photo Only | - | - |
|  | Left Side Panel | Photo Only | - | - |
|  | Right Side Panel | Photo Only | - | - |
|  | Front Cover Center | Photo Only | - | - |
|  | Keys | Photo Only | - | - |
|  | Engine | Photo Only | - | - |
|  | Photo - Vin/Id Sticker | Photo Only | - | - |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Rear Cargo Door | Dent(S) W/ Paint Dmg | - | 1 To 2 Inches |
|  | Left Front Center Cap | Missing | - | Replacement Required |
|  | Left Front Seat Cushion | Torn | - | 4 To 5 Inches |
|  | Front Bumper | Gouged | - | 3 To 4 Inches |
|  | Left Rear Cargo Door | Dent(S) W/ Paint Dmg | - | 7 To 8 Inches |
|  | Right Head Lamp | Faded | - | Repair Required |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Left Head Lamp | Faded | - | Repair Required |
|  | Left Front Door | Dent(S) W/No Paint Dmg | - | Pdr-1 Dent |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.