



Approved CR

Dealers Auto Auction of Mobile
3030 McVay Drive North
Mobile, AL 36606
2513387653
WHOLESALE ASSESSMENT ONLY

Make/Model: **2023 RAM
2500
Crew Cab**
Bodystyle/Series: **TRADESMAN
CREW CAB
4WD LWB**
Color: **RED**
Mileage: **107,174
(Verified, 6
digits)**
Turn-in Mileage: **-**
VIN: **3C6UR5HJXPG632227**
Work Order/
Stock Number: **000594350**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **-**
Vehicle Grade : **Grade 3.9**
AutoGrade : **3.9 - Average**
Remarks: **-**
Announcements: **-**
Certification : **Not Certified**
Req. Prev. Repair **-**
Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: YES

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.4 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment


Additional Equipment:

4 Wheel Drive	4 Wheel Drive	ABS Brakes
Air Conditioning	Automatic Headlights	Bluetooth Connection
Brake Assist System	Car Tire Size - Hood	Car Tire Size - RR tire size LT275/70RR18
Car Tire Size - RF tire size LT275/70RR18	Car Tire Size - LR tire size LT275/70RR18	Car Tire Size - LF tire size LT275/70RR18
Child Safety Locks	Cruise Control	Cylinders - 8
Daytime Running Lights	Driver Air Bag	Engine Immobilizer
Floor Mats	Heated Mirrors	Intermittent Wipers
Keyless Start	LF Tires - 6/32 inch	LR Tires - 6/32 inch
MP3 Radio	Master Key - 2key(s)	Motor Fuel Type - Gas
Pass. Air Bag	Power Brakes	Power Lock
Power Mirrors	Power Steering	Power Windows
Privacy Glass	RF Tires - 6/32 inch	RR Tires - 6/32 inch
Rear Defrost	Reverse Camera	Running Board
Seat Trim - Cloth	Side Airbags - Front	Smart Key - 2key(s)
Spare Tire	Stereo - AM/FM Radio	Telematics
Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Other	Tire Brand - Front Left - L qtr panel
Tire Brand - Front Right - RF tire mfg Other	Tire Brand - Rear Left - LR tire mfg Other	Tire Brand - Rear Right - RR tire mfg Other
Tire Pressure Monitor System	Tow Hitch	Traction Control
Transmission - Automatic Transmission	Turn Signal Mirrors	Wheels Front Left - Steel
Wheels Front Right - Steel	Wheels Rear Left - Steel	Wheels Rear Right - Steel
XM Radio		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Trunk	Photo Only	Estimate Only	Unknown
	Left Front Fender	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	Estimate Only	Unknown
	Right Qtr Panel	Photo Only	Estimate Only	Unknown
	Left Qtr Panel	Photo Only	Estimate Only	Unknown
	Hood	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown

Chargeable Damages

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	Repair	7
	Hood	Chipped	Repair	5
	Left Bed Side	Heavy Scratch	Repair	4 To 5 Inches
	Left Front Door	Dent(S) W/No Paint Dmg	Repair	1 To 2 Inches
	Left Rear Door	Multiple Scratches Heavy	Repair	4
	Rear Bumper	Multiple Scratches Heavy	Repair	6
	Tailgate	Dent(S) W/No Paint Dmg	Repair	1 To 2 Inches
	Windshield	Star In Glass	Replace	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.