Approved
CR

Orlando Auto Auction
4636 W. Colonial Dr
Orlando, FL 32808
(407) 299-3904/(407) 294-6982
david.orlandoautoauction@gmail.com
WHOLESALE ASSESSMENT ONLY



| | |
|---|---|
| Make/Model: | **2020 FORD TRANSIT CONNECTP** |
| Bodystyle/Series: | **5 Door Station Wagon XL** |
| Color: | **GRAY** |
| Mileage: | **66,648 (Digital)** |
| Turn-in Mileage: | - |
| VIN: | **NM0GE9E28L1480850** |
| Work Order/ Stock Number: | **0318660** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | **G412235X** |
| Vehicle Grade : | **Grade 3.4** |
| Remarks: | - |
| Announcements: | • DEFICIENCIES, WHEN KNOWN, HAVE BEEN NOTED IN THE<br>• ITEM DESCRIPTION; HOWEVER, THE ABSENCE OF ANY<br>• INDICATED DEFICIENCIES DOES NOT MEAN THERE ARE<br>• NONE. |
| Certification : | **Not Certified** |
| Req. Prev. Repair Order: | - |

Drivable: Yes

As Is 100K Miles: NO

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Automatic Transmission w/ Overdrive** | A/C: | **Yes** |
| Engine: | **4-Cylinder Gas** | Cruise Control: | **Yes** |

## Equipment

| | | | |
|---|---|---|---|
| Engine Size: | **2 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **Yes** |
| Radio: | - | Pwr Windows | **Yes** |
| Interior - Type/Color: | - /**BLACK** | Rear Defroster: | **Yes** |
| Airbag: | **Driver Side Air Bag** | Tilt Steering: | **No** |
| Seats: | **Buckets** | Drive Type: | **Front Wheel Drive** |
| Seat Count: | **0** | Brakes: | **Power Brakes** |

Additional Equipment:

| | | |
|---|---|---|
| 3rd Row Seat | 4th Passenger Door | Automatic Headlights |
| Auxiliary Audio Input | Auxiliary Pwr Outlet | Backup camera and monitor |
| Bluetooth Connection | Brake Assist System | Car LF Tires - 8/32 inch |
| Car LR Tires - 8/32 inch | Car RF Tires - 8/32 inch | Car RR Tires - 7/32 inch |
| Car Tire Size - LF: P215/55HR16 LR: P215/55HR16 RF: P215/55HR16 RR: P215/55HR16 | Child Safety Locks | Cylinders - 4 |
| Daytime Running Lights | Driver Adjustable Lumbar | Electronic Stability Control |
| Engine Immobilizer | Floor Mats | Forward Collision Alert System |
| Front Head Air Bag | Ignition Key - 1key(s) | Independent Climate Control |
| Intermittent Wipers | Keyless Entry - Left | LF Tires - 8/32 inch |
| LR Tires - 8/32 inch | Misc. Special Features - Passenger Third Door, Airbag Disconnect Switch, Automatic Highbeams | Pass-Through Rear Seat |
| Pass. Air Bag | Passenger Air Bag Sensor | Privacy Glass |
| RF Tires - 8/32 inch | RR Tires - 7/32 inch | Rain Sensor |
| Rear AC | Rear Head Air Bag | Rear Parking Aid |
| Side Airbags - Front | Smart Device Integration | Tilt Steering Wheel |
| Tire Brand - Front Left - OTHER | Tire Brand - Front Right - OTHER | Tire Brand - Rear Left - OTHER |
| Tire Brand - Rear Right - COOPER | Tire LF - 8/32 inch | Tire Pressure Monitor System |
| Tire RF - 8/32 inch | Tire Size - LF: P215/55HR16 LR: P215/55HR16 RF: P215/55HR16 RR: P215/55HR16 | Tire Size - LF: P215/55HR16 LR: P215/55HR16 RF: P215/55HR16 RR: P215/55HR16 |
| Transmission - Automatic Transmission w/ Overdrive | Trip Computer | Wheels Front Left - Steel |
| Wheels Front Right - Steel | Wheels Rear Left - Steel | Wheels Rear Right - Steel |
| WiFi Hotspot | | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Extra Photo 9 | Photo Only | - | - |
|  | Extra Photo 8 | Photo Only | - | - |
|  | Extra Photo 7 | Photo Only | - | - |
|  | Extra Photo 6 | Photo Only | - | - |
|  | Extra Photo 5 | Photo Only | - | - |
|  | Extra Photo 4 | Photo Only | - | - |
|  | Extra Photo 3 | Photo Only | - | - |
|  | Extra Photo 2 | Photo Only | - | - |
|  | Extra Photo 1 | Photo Only | - | - |
|  | Miscellaneous | Photo Only | - | - |
|  | Miscellaneous | Photo Only | - | - |
|  | Miscellaneous | Photo Only | - | - |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Shifter Knob | Worn | Replace | Replacement Required |
|  | Rear View Mirror | Broken | Replace | Replacement Required |
|  | Right Rear Wheel Cover | Missing | Replace | Replacement Required |
|  | Right Qtr Panel | Dent(S) W/ Paint Dmg | Repair | 5 To 6 Inches |
|  | Right Rear Door | Multiple Dents/Paint Damage | Repair | 4 |
|  | Gas Cap | Missing | Replace | Replacement Required |
|  | Rear Bumper/Cover | Gouged | Replace | 4 To 5 Inches |
|  | Left Rear Door | Multiple Dents/Paint Damage | Repair | 2 |
|  | Left Front Door | Multiple Dents/No Paint Damage | PDR | Pdr-2 Dents |
|  | Right Head Lamp | Faded | Repair | Repair Required |
|  | Left Head Lamp | Faded | Repair | Repair Required |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.