



Approved
CR

United Auto Exchange
3710 Prescott Rd
Memphis, TN 38118
9017957634
jcraig@uaxmemphis.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 RAM
2500**
Bodystyle/Series: **4 Door Vehicle
TRADESMAN**
Color: **SILVER**
Mileage: **54,188
(Verified, 6
digits)**
Turn-in Mileage: **-**
VIN: **3C6UR5HJ2HG744179**
Work Order/
Stock Number: **000081834**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G631945U**
Vehicle Grade : **Grade 2.3**
Remarks: **-**

Announcements:

• DEFICIENCIES,
WHEN
KNOWN,
HAVE BEEN
NOTED IN THE
ITEM
DESCRIPTION
• HOWEVER,
THE ABSENCE
OF ANY
INDICATED
DEFICIENCIES
• DOES NOT
MEAN THERE
ARE NONE.

Certification : **Not Certified**
Req. Prev. Repair **-**
Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	No

Equipment

Engine Size:	6.4 L	Pwr Steering:	No
Roof:	Hard Top	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	-	Tilt Steering:	No
Seats:	-	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	-

Additional Equipment:

4 Wheel Drive	4 Wheel Drive	Car Tire Size - RR tire size 265/70R17
Car Tire Size - RF tire size 265/70R17	Car Tire Size - LF tire size 265/70R17	Car Tire Size - LR tire size 265/70R17
Cylinders - 8	LF Tires - 12/32 inch	LR Tires - 11/32 inch
Master Key - 1key(s)	Motor Fuel Type - Gas	RF Tires - 12/32 inch
RR Tires - 11/32 inch	Seat Trim - Cloth	Tire Brand - Front Left - LF tire mfg Generic
Tire Brand - Front Right - RF tire mfg COOPER	Tire Brand - Rear Left - LR tire mfg Generic	Tire Brand - Rear Right - RR tire mfg Generic
Transmission - Automatic Transmission	Wheels Front Left - Aluminium	Wheels Front Right - Aluminium
Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Frame	Photo Only	Estimate Only	Unknown
	Extra Photo 7	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Multiple Scratches Light	Report	10 Or More
	Left Bed Side	Dent(S) W/ Paint Dmg	Repair	> 12 Inches
	Cab - Left	Multiple Scratches Heavy	Report	4
	Left Front Door	Dent(S) W/ Paint Dmg	Repair	1/2 To 1 Inch
	Left Front Fender	Dent(S) W/ Paint Dmg	Repair	1/2 To 1 Inch
	Left Front Seat Cushion	Torn	Replace	> 12 Inches
	Left Rear Door	Multiple Scratches Light	Report	5
	Right Bed Side	Dent(S) W/ Paint Dmg	Repair	> 12 Inches
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	Repair	5 To 6 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Scuffed	Report	> 12 Inches
	Right Front Fender	Dent(S) W/ Paint Dmg	Repair	1/2 To 1 Inch
	Right Front Seat Cushion	Burn Hole	Replace	1/2 To 1 Inch
	Right Rear Door	Light Scratch	Report	> 12 Inches
	Tailgate Protective Cap	Missing	Replace	Replacement Required
	Tailgate	Multiple Dents/Paint Damage	Repair	6

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.