



Approved CR

IAA Denver East  
8510 Brighton Rd.  
Branch No 374  
Commerce City, CO 80022  
(303) 287-9737/(303) 287-1214  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 BLUE  
BIRD  
SCHOOL  
BUS /  
TRANSIT  
BUS**

Bodystyle/Series: - -

Color: **White**

Mileage: **51,826  
(Verified)**

Turn-in Mileage: -

VIN: **1BABNBCA2HF323687**

Work Order/  
Stock Number: **46376937**

Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalessupport@gsa.gov**

Client Stock #: **G32B0385**

Vehicle Grade : **Grade 2.8**

Remarks: -

Announcements: 

• TIRES  
WORN

Certification : -

Req. Prev. Repair -

Order: -



Drivable: Yes

### Equipment

|                        |                   |                 |                  |
|------------------------|-------------------|-----------------|------------------|
| Transmission:          | -                 | A/C:            | No               |
| Engine:                | 6-Cylinder Diesel | Cruise Control: | No               |
| Engine Size:           | 8.9 L             | Pwr Steering:   | No               |
| Roof:                  | -                 | Pwr Locks:      | No               |
| Radio:                 | -                 | Pwr Windows     | No               |
| Interior - Type/Color: | - / -             | Rear Defroster: | No               |
| Airbag:                | -                 | Tilt Steering:  | No               |
| Seats:                 | -                 | Drive Type:     | Rear Wheel Drive |
| Seat Count:            | -                 | Brakes:         | -                |
| Additional Equipment:  | -                 |                 |                  |

### Non Chargeable Damages

| Photo                                                                               | Item                   | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|------------------------|------------|--------|----------|
|    | Rear Seats             | Photo Only | -      | -        |
|    | Photo - Vin/Id Sticker | Photo Only | -      | -        |
|    | Engine                 | Photo Only | -      | -        |
|    | Keys                   | Photo Only | -      | -        |
|   | Front Cover Center     | Photo Only | -      | -        |
|  | Right Side Panel       | Photo Only | -      | -        |
|  | Left Side Panel        | Photo Only | -      | -        |
|  | Instrument Panel       | Photo Only | -      | -        |
|  | Rear Bumper            | Photo Only | -      | -        |
|  | Right Front Fender     | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                              | Item                    | Damage     | Action | Severity |
|------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
|   | Left Front Fender       | Photo Only | -      | -        |
|   | Left Rear Bumper/Cover  | Photo Only | -      | -        |
|   | Right Rear Bumper/Cover | Photo Only | -      | -        |
|   | Photo - Dash            | Photo Only | -      | -        |
|   | Extra Photo 1           | Photo Only | -      | -        |
|  | Odometer                | Photo Only | -      | -        |

### Chargeable Damages

| Photo                                                                               | Item             | Damage      | Action | Severity             |
|-------------------------------------------------------------------------------------|------------------|-------------|--------|----------------------|
|  | Right Front Tire | Worn        | -      | Replacement Required |
|  | Overall Vehicle  | De-Identify | -      | Removal Required     |

### Chargeable Damages

| Photo                                                                               | Item                       | Damage  | Action | Severity             |
|-------------------------------------------------------------------------------------|----------------------------|---------|--------|----------------------|
|    | Left Front Tire            | Worn    | -      | Replacement Required |
|    | Left Rear Tire             | Worn    | -      | Replacement Required |
|    | R Running Board Step Pad   | Broken  | -      | Replacement Required |
|   | Hood                       | Peeling | -      | > 12 Inches          |
|  | Front Metal Bumper Painted | Rust    | -      | 1 To 2 Inches        |
|  | Right Side Panel           | Rust    | -      | 9 To 10 Inches       |

| Chargeable Damages                                                                |                 |        |        |                      |
|-----------------------------------------------------------------------------------|-----------------|--------|--------|----------------------|
| Photo                                                                             | Item            | Damage | Action | Severity             |
|  | Right Rear Tire | Worn   | -      | Replacement Required |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.