Approved CR

IAA Salt Lake City
1800 South 1100 West
Branch No 342
Ogden, UT 84401-0258
(801) 399-2818/(801) 393-2325
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2020 DODGE GRAND CARAVAN**
Bodystyle/Series:	**Van SE**
Color:	**Black**
Mileage:	**66,185 (Verified)**
Turn-in Mileage:	-
VIN:	**2C4RDGBG7LR197886**
Work Order/ Stock Number:	**46378768**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G410501X**
Vehicle Grade :	**Grade 3.8**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 65 R 17	Car Tire Size - RF 225 / 65 R 17	Car Tire Size - LF 225 / 65 R 17
Car Tire Size - LR 225 / 65 R 17	LF Tires - 5/32 inch	LR Tires - 8/32 inch
RF Tires - 5/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - LAUFENN
Tire Brand - Front Right - Unknown	Tire Brand - Rear Left - LAUFENN	Tire Brand - Rear Right - Unknown
Tire Model - LF - G Fit As (LH41)	Tire Model - LR - G Fit As (LH41)	Tire Model - RF - G Fit As (LH41)
Tire Model - RR - G Fit As (LH41)		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Tire Pressure	On	-	Unacceptable
	Instrument Panel	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel Cover	Bent	-	Replacement Required
	Left Qtr Panel	Chipped	-	1
	Right Front Wheel Cover	Bent	-	Replacement Required
	Hood	Multiple Scratches Heavy	-	5
	Front Bumper	Dent(S) W/ Paint Dmg	-	< 1/8 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Door	Chipped	-	10 Or More
	Left Front Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.