



Approved
CR

Rawls Auto Auction Inc.
2818 Pond Branch Rd.
Leesville, SC 29070
(803) 859-5111/(803) 859-0517
wendyc@rawlsautoauction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 FORD
F-450 CHASSIS**

Bodystyle/Series: **2 Door Vehicle
XLT**

Color: **WHITE**

Mileage: **101,735 (Verified,
6 digits)**

Turn-in Mileage: **-**

VIN: **1FDUF4GT9GEC32743**

Work Order/
Stock Number: **000378546**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G310120S**

Vehicle Grade : **Grade 3.5**

Remarks: **-**

Announcements:

- POWERSTROKE
- AMBULANCE

Certification : **Not Certified**

Req. Prev. Repair
Order: **-**



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: YES

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	8-Cylinder Diesel Turbo	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

ABS Brakes	Adjustable Pedals	Air Conditioning
Auxiliary Pwr Outlet	Bench Seating	Bluetooth Connection
Car Tire Size - RR tire size LT225/70SR19.5	Car Tire Size - LR tire size LT225/70SR19.5	Car Tire Size - LF tire size LT225/70SR19.5
Car Tire Size - RF tire size LT225/70SR19.5	Cruise Control	Cylinders - 8
Daytime Running Lights	Driver Air Bag	Dual Rear Wheels
Empty Weight - 6925 lb	Engine Immobilizer	Heated Mirrors
Independent Climate Control	Intermittent Wipers	Keyless Entry
LF Tires - 14/32 inch	LR Tires - 9/32 inch	LR Tires - 7/32 inch
MP3 Radio	Master Key - 1key(s)	Motor Fuel Type - Diesel
OK Odor	Owner's Manual	Pass. Air Bag
Power Brakes	Power Lock	Power Mirrors
Power Steering	Power Windows	Privacy Glass
RF Tires - 14/32 inch	RR Tires - 8/32 inch	Rear View Mirror
Seat Trim - Cloth	Security System	Side Airbags - Front
Steering Wheel Audio Control	Stereo - AM/FM Radio	Tilt Steering Wheel
Tilt Wheel	Tire Brand - Front Left - LF tire mfg Toyo	Tire Brand - Front Right - RF tire mfg Toyo
Tire Brand - Rear Left - LR tire mfg Yokohama	Tire Brand - Rear Right - RR tire mfg Yokohama	Traction Control
Transmission - Automatic Transmission w/ Overdrive	Turbocharged	Turn Signal Mirrors
Two-Wheel Drive	Warranty Books	Wheels Front Left - Steel
Wheels Front Right - Steel	Wheels Rear Left - Steel	Wheels Rear Right - Steel

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Extra Photo 6	Photo Only	Estimate Only	Unknown
	Extra Photo 7	Photo Only	Estimate Only	Unknown
	Extra Photo 8	Photo Only	Estimate Only	Unknown
	Extra Photo 9	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Door Panels	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
[no photo]	Right Hood Strut	Inoperable	Replace	Replacement Required
[no photo]	Warranty Book	Missing	Replace	Replacement Required
[no photo]	Left Head Lamp	Faded	Refinish	Repair Required
[no photo]	Left Front Seat	Torn	Repair	1/2 To 1 Inch
[no photo]	Overall Vehicle	Multiple Scratches Light	Wet Sand	10 Or More
[no photo]	Right Head Lamp	Faded	Refinish	Repair Required
[no photo]	Hood	Chipped	Touch Up	5
[no photo]	Left Front Door	Dent(S) W/ Paint Dmg	Report	1/2 To 1 Inch
[no photo]	Right Front Door	Dent(S) W/No Paint Dmg	PDR	Pdr-1 Dent
[no photo]	Steering Wheel	Worn	Report	Acceptable
	Left Bed Side	Multiple Dents/Paint Damage	Repair	3
	Left Front Center Cap	Missing	Replace	Replacement Required
	Rear Bumper	Dent(S) W/No Paint Dmg	Repair	2 To 3 Inches
	Rear View Mirror	Aftermarket	Report	Acceptable
	Right Front Center Cap	Missing	Replace	Replacement Required
[no photo]	Left Hood Strut	Inoperable	Replace	Replacement Required
[no photo]	Maintenance Book	Missing	Replace	Replacement Required
[no photo]	Owners Manual	Missing	Replace	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Center Console	Aftermarket	Report	Acceptable
	Front Bumper	Aftermarket	Report	Acceptable
	Grille	Aftermarket	Report	Acceptable
	Headlining	Aftermarket	Report	Acceptable
	Bluetooth	Inoperable	Report	Repair Required
	Cargo Shelf	Missing	Replace	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.