Approved CR

IAA Portland
4415 NE 158th Avenue
Branch No 308
Portland, OR 97230
(503) 253-1500/(503) 253-9359
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 FORD EXPEDITION**
Bodystyle/Series:	**Sport Utility Vehicle XL**
Color:	**White**
Mileage:	**83,717 (Verified)**
Turn-in Mileage:	-
VIN:	**1FMJU1GT1LEA89160**
Work Order/ Stock Number:	**46438279**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G625941X**
Vehicle Grade :	**Grade 4.2**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3.5 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Power - Driver Only**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - RR 275 / 65 R 18	Car Tire Size - RF 275 / 65 R 18	Car Tire Size - LF 275 / 65 R 18
Car Tire Size - LR 275 / 65 R 18	LF Tires - 16/32 inch	LR Tires - 14/32 inch
RF Tires - 15/32 inch	RR Tires - 16/32 inch	Tire Brand - Front Left - FALKEN
Tire Brand - Front Right - FALKEN	Tire Brand - Rear Left - FALKEN	Tire Brand - Rear Right - FALKEN
Tire Model - LF - Wildpeak A/T4W	Tire Model - LR - Wildpeak A/T4W	Tire Model - RF - Wildpeak A/T4W
Tire Model - RR - Wildpeak A/T4W		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	3 To 4 Inches
	Right Front Door	Chipped	-	2
	Right Rear Wheel	Curb Rash	-	2 To 3 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.