



Approved CR

IAA Indianapolis South
1947 S County Rd (SCR) 1240E
Branch No 548
Crothersville, IN 47229
(317) 536-8231
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018
CHEVROLET
SILVERADO
2500HD**

Bodystyle/Series: **Crew Cab
WT**

Color: **Silver**

Mileage: **62,872
(Verified)**

Turn-in Mileage: **-**

VIN: **1GC1KUEG1JF258554**

Work Order/
Stock Number: **46356775**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G630900V**

Vehicle Grade : **Grade 3.8**

Remarks: **-**

Announcements:

**• WHEEL
CORROSION**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 17

Car Tire Size - RF 245 / 75 R 17

Car Tire Size - LF 245 / 75 R 17

Car Tire Size - LR 245 / 75 R 17

LF Tires - 5/32 inch

LR Tires - 8/32 inch

RF Tires - 8/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - MASTERCRAFT

Tire Brand - Front Right - MASTERCRAFT

Tire Brand - Rear Left - MASTERCRAFT

Tire Brand - Rear Right - MASTERCRAFT

Tire Model - RR - Courser HXT

Tire Model - LF - Courser HXT

Tire Model - LR - Courser HXT

Tire Model - RF - Courser HXT

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable
	Tonneau Cover	Aftermarket	-	Acceptable
	Engine	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Corrosion	-	> 12 Inches
	Left Rear Wheel	Corrosion	-	9 To 10 Inches
	Tailgate	Multiple Dents/Paint Damage	-	3
	Right Rear Wheel	Corrosion	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.