



Approved
CR

IAA Providence
160 Amaral St
Branch No 644
Riverside, RI 02915
(401) 438-5254/(401) 438-3523
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 MACK
PINNACLE**
Bodystyle/Series: **Cab/Chassis -**
Color: **-**
Mileage: **273,365 (Verified)**
Turn-in Mileage: **-**
VIN: **1M1AW07YXHM083181**
Work Order/
Stock Number: **45590143**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G820153S**
Vehicle Grade : **Grade 2.8**
Remarks: **-**
Announcements:

**• ANNOUNCEMENTS:
Uneconomical to
Repair**

Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	-	A/C:	Yes
Engine:	6-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	12.7 L	Pwr Steering:	No
Roof:	Hard Top	Pwr Locks:	No
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Vinyl Interior /-	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	No
Seats:	-	Drive Type:	-
Seat Count:	-	Brakes:	Air Brakes

Equipment



Additional Equipment:

Car Tire Size - LF 245 / 80 R 22.5	Car Tire Size - LR 275 / 80 R 22.5	Car Tire Size - RR 245 / 80 R 22.5
Car Tire Size - RF 245 / 80 R 22.5	LF Tires - 10/32 inch	LR Tires - 16/32 inch
RF Tires - 16/32 inch	RR Tires - 16/32 inch	Tire Brand - Front Left - MICHELIN
Tire Brand - Front Right - MICHELIN	Tire Brand - Rear Left - MICHELIN	Tire Brand - Rear Right - MICHELIN
Tire Model - RR - XDN2 Grip	Tire Model - RF - XDN2 Grip	Tire Model - LR - XDN2 Grip
Tire Model - LF - XDN2 Grip		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Rust	-	Repair Required
	Left Rear Wheel	Rust	-	Repair Required
	Hood	Peeling	-	3 To 4 Inches
	Left Front Wheel	Rust	-	Repair Required
	Exhaust	Broken	-	Replacement Required
	Front Spoiler	Broken	-	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Head Lamp	Faded	-	Repair Required
	Left Head Lamp	Faded	-	Repair Required
	Right Front Wheel	Rust	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.