Approved CR

IAA Macon
2200 Trade Ave.
Branch No 734
Macon, GA 31217
(478) 314-0031/(478) 314-0040
WHOLESALE ASSESSMENT ONLY




| | |
|---|---|
| Make/Model: | **2022 FORD ESCAPE** |
| Bodystyle/Series: | **Sport Utility Vehicle SE PLUG-IN HYBRID** |
| Color: | **Gray** |
| Mileage: | **114,809 (Verified)** |
| Turn-in Mileage: | - |
| VIN: | **1FMCU0EZ0NUA90786** |
| Work Order/ Stock Number: | **46159267** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | **G410133Z** |
| Vehicle Grade : | **Grade 1.3** |
| Remarks: | - |
| Announcements: | - |
| Certification : | - |
| Req. Prev. Repair Order: | - |

Drivable: Yes

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Continuously Variable Transmission** | A/C: | **No** |
| Engine: | **4-Cylinder Hybrid** | Cruise Control: | **Yes** |
| Engine Size: | **2.5 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **Yes** |
| Radio: | - | Pwr Windows | **Yes** |
| Interior - Type/Color: | **Cloth/Vinyl /GRAY** | Rear Defroster: | **Yes** |
| Airbag: | **Driver Side Air Bag** | Tilt Steering: | **Yes** |
| Seats: | **Buckets** | Drive Type: | **Front Wheel Drive** |
| Seat Count: | - | Brakes: | **Anti Lock Brakes** |

## Equipment

Additional Equipment:

| | | |
|---|---|---|
| Car Tire Size - LF 225 / 60 R 18 | Car Tire Size - LR 225 / 60 R 18 | Car Tire Size - RR 225 / 60 R 18 |
| Car Tire Size - RF 225 / 60 R 18 | LF Tires - 7/32 inch | LR Tires - 6/32 inch |
| RF Tires - 7/32 inch | RR Tires - 7/32 inch | Tire Brand - Front Left - MICHELIN |
| Tire Brand - Front Right - MICHELIN | Tire Brand - Rear Left - MICHELIN | Tire Brand - Rear Right - MICHELIN |
| Tire Model - RR - Defender 2 | Tire Model - RF - Defender 2 | Tire Model - LR - Defender 2 |
| Tire Model - LF - Defender 2 | | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Rear Seats | Photo Only | - | - |
|  | Photo - Dash | Photo Only | - | - |
|  | Extra Photo 1 | Photo Only | - | - |
|  | Odometer | Photo Only | - | - |
|  | Left Apron | Broken | - | Replacement Required |
|  | Warning - Traction Control | On | - | Unacceptable |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Warning Light - Abs | On | - | Unacceptable |
|  | Warning Light - Brakes | On | - | Unacceptable |
|  | Warning Light - Air Bag | On | - | Unacceptable |
|  | Photo - Vin/Id Sticker | Photo Only | - | - |
|  | Engine | Photo Only | - | - |
|  | Keys | Photo Only | - | - |
|  | Front Cover Center | Photo Only | - | - |
|  | Right Side Panel | Photo Only | - | - |
|  | Left Side Panel | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Instrument Panel | Photo Only | - | - |
|  | Rear Bumper | Photo Only | - | - |
|  | Extra Photo 2 | Photo Only | - | - |
|  | Extra Photo 3 | Photo Only | - | - |
|  | Right Front Fender | Photo Only | - | - |
|  | Extra Photo 4 | Photo Only | - | - |
|  | Extra Photo 5 | Photo Only | - | - |
|  | Extra Photo 6 | Photo Only | - | - |
|  | Extra Photo 7 | Photo Only | - | - |
|  | Left Front Fender | Photo Only | - | - |
|  | Left Rear Bumper/Cover | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Rear Bumper/Cover | Photo Only | - | - |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Front Wheel | Curb Rash | - | 9 To 10 Inches |
|  | Right Rear Wheel | Curb Rash | - | 7 To 8 Inches |
|  | Left Rear Door | Dent(S) W/No Paint Dmg | - | 1/2 To 1 Inch |
|  | Left Rear Wheel | Curb Rash | - | 5 To 6 Inches |
|  | Left Front Fender | Severe Damage | - | Replacement Required |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Left Head Lamp | Misaligned | - | Repair Required |
|  | Front Bumper | Broken | - | Replacement Required |
|  | Left Front Wheel | Curb Rash | - | 2 To 3 Inches |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.