



Approved CR

IAA Tulsa
5311 W 46th Street S
Branch No 436
Tulsa, OK 74107
(918) 445-4691/(918) 445-4905
WHOLESALE ASSESSMENT ONLY

2012
Make/Model: **INTERNATIONAL**
7000
Bodystyle/Series: - **7600**
Color: **Silver**
Mileage: **84,246**
(Verified)
Turn-in Mileage: -
VIN: **1HSGRSJR8CJ591987**
Work Order/
Stock Number: **46364775**
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: -
Vehicle Grade : **Grade 2.9**
Remarks: -
Announcements: -
Certification : -
Req. Prev. Repair
Order: -



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	6-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	13 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Air Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 11 / 0 R 22.5

Car Tire Size - RF 11 / 0 R 22.5

Car Tire Size - LF 11 / 0 R 22.5

Car Tire Size - LR 11 / 0 R 22.5

LF Tires - 19/32 inch

LR Tires - 13/32 inch

RF Tires - 20/32 inch

RR Tires - 11/32 inch

Tire Brand - Front Left - MICHELIN

Tire Brand - Front Right - MICHELIN

Tire Brand - Rear Left - MICHELIN

Tire Brand - Rear Right - MICHELIN

Tire Model - RR - XZE2

Tire Model - RF - XZE2

Tire Model - LR - XZE2

Tire Model - LF - XZE2

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Bumper	Aftermarket	-	Removal Required
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Seat Cushion	Torn	-	> 12 Inches
	Roof Panel	Chipped	-	2
	Right Front Wheel	Curb Rash	-	> 12 Inches
	Right Front Fender	Peeling	-	> 12 Inches
	Hood	Peeling	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.