



Approved CR

IAA Tulsa
5311 W 46th Street S
Branch No 436
Tulsa, OK 74107
(918) 445-4691/(918) 445-4905
WHOLESALE ASSESSMENT ONLY

2012
Make/Model: **INTERNATIONAL**
7000
Bodystyle/Series: - **7600**
Color: **Gray**
Mileage: **87,272**
(Verified)
Turn-in Mileage: -
VIN: **1HSGRSJR9CJ591982**
Work Order/
Stock Number: **46364749**
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: -
Vehicle Grade : **Grade 3.1**
Remarks: -
Announcements: -
Certification : -
Req. Prev. Repair
Order: -



Drivable: Yes

Equipment


Transmission:	-	A/C:	No
Engine:	6-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	13 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Synthetic Leather /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Air Brakes


Equipment

Additional Equipment:

Car Tire Size - RR 12 / 0 R 22.5	Car Tire Size - LF 12 / 0 R 22.5	Car Tire Size - RF 12 / 0 R 22.5
Car Tire Size - LR 12 / 0 R 22.5	LF Tires - 17/32 inch	LR Tires - 14/32 inch
RF Tires - 18/32 inch	RR Tires - 18/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - FIRESTONE
Tire Model - LF - FS561A	Tire Model - RR - FS561	Tire Model - RF - FS561
Tire Model - LR - FS561		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Rust	-	2 To 3 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Hood	Peeling	-	> 12 Inches
	Roof	Oxidized	-	> 12 Inches
	Left Front Wheel	Corrosion	-	> 12 Inches
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Rear Mud Guard	Bent	-	> 12 Inches
	Right Rear Mud Guard	Bent	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	9 To 10 Inches
	Right Rear Wheel	Curb Rash	-	7 To 8 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.