



Approved CR

IAA Tulsa
5311 W 46th Street S
Branch No 436
Tulsa, OK 74107
(918) 445-4691/(918) 445-4905
WHOLESALE ASSESSMENT ONLY

2012
Make/Model: **INTERNATIONAL**
7000
Bodystyle/Series: - **7600**
Color: **Gray**
Mileage: **93,183**
(Verified)
Turn-in Mileage: -
VIN: **1HSGRSJR0CJ591983**
Work Order/
Stock Number: **46364729**
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: -
Vehicle Grade : **Grade 2.0**
Remarks: -
Announcements: -
Certification : -
Req. Prev. Repair -
Order: -



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	6-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	13 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Vinyl Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Air Brakes

Equipment

Additional Equipment:

Car Tire Size - LR 0 / 12 R 22.5

Car Tire Size - RR 0 / 12 R 22.5

Car Tire Size - RF 0 / 12 R 22.5

Car Tire Size - LF 0 / 12 R 22.5

LF Tires - 3/32 inch

LR Tires - 19/32 inch

RF Tires - 9/32 inch

RR Tires - 7/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - LF - FS561




Tire Model - LR - FS561

Tire Model - RF - FS561

Tire Model - RR - FS561

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Cab - Left	Peeling	-	4 To 5 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Curb Rash	-	7 To 8 Inches
	Left Front Tire	Worn	-	Replacement Required
	Roof	Peeling	-	> 12 Inches
	Left Front Door	Peeling	-	4 To 5 Inches
	Right Front Door	Peeling	-	> 12 Inches
	Front Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Peeling	-	> 12 Inches
	Right Front Wheel	Curb Rash	-	6 To 7 Inches
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Right Rear Mud Guard	Bent	-	4 To 5 Inches
	Left Rear Mud Guard	Bent	-	3 To 4 Inches
	Left Rear Wheel	Corrosion	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Multiple Scratches Heavy	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.