



Approved
CR

IAA North Virginia
15 Le Way Drive
Branch No 723
Fredericksburg, VA 22406
(540) 373-7800/(540) 371-4123
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 DODGE
GRAND CARAVAN**
Bodystyle/Series: **Van SE**
Color: **White**
Mileage: **22,554 (Verified)**
Turn-in Mileage: **-**
VIN: **2C4RDGBG6HR736652**
Work Order/
Stock Number: **46390846**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G410098U**
Vehicle Grade : **Grade 2.9**
Remarks: **-**
Announcements: **• ANNOUNCEMENTS:**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment


Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 65 R 17	Car Tire Size - LR 225 / 65 R 17	Car Tire Size - RR 225 / 65 R 17
Car Tire Size - RF 225 / 65 R 17	LF Tires - 4/32 inch	LR Tires - 6/32 inch
RF Tires - 6/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - YOKOHAMA	Tire Brand - Rear Right - FIRESTONE
Tire Model - RR - All Season	Tire Model - RF - All Season	Tire Model - LR - Avid S33
Tire Model - LF - All Season		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Dent(S) W/ Paint Dmg	-	8 To 9 Inches
	Hood	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Right Head Lamp	Cracked	-	Replacement Required
	Right Front Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Rear Bumper	Dent(S) W/ Paint Dmg	-	9 To 10 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Qtr Panel	Scuffed	-	3 To 4 Inches
	Left Front Wheel Cover	Curb Rash	-	2 To 3 Inches
	Lift Gate	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Right Front Wheel Cover	Curb Rash	-	8 To 9 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.