



Approved CR

America's Auto Auction - Pensacola, Inc
6615 Mobile Highway
Pensacola, FL 32526-1264
850-972-8601/(850) 944-8482
Della.Smith@AmericasAutoAuction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019
CHEVROLET
SUBURBAN**

Bodystyle/Series: **4 Door Sport
Utility
Vehicle LS
4D SUV
RWD**

Color: **BLACK**

Mileage: **41,624
(Verified, 6
digits)**

Turn-in Mileage: -

VIN: **1GNSCGKC3KR197395**

Work Order/
Stock Number: **000354949**

Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov

Client Stock #: **G422560V**

Vehicle Grade : **Grade 4.0**

Remarks: -

Announcements: -

Certification : **Not Certified**

Req. Prev. Repair
Order: -



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	5.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM CD	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	Power	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

3rd Row Seat	ABS Brakes	Air Conditioning
Automatic Headlights	Bluetooth Connection	Brake Assist System
CD Player	Car Tire Size - LR tire size P265/65R18	Car Tire Size - LF tire size P265/65R18
Car Tire Size - RF tire size P265/65R18	Car Tire Size - RR tire size P265/65R18	Child Safety Locks
Cruise Control	Cylinders - 8	Daytime Running Lights
Driver Air Bag	Dual Air Conditioning	Floor Mats
Front Reading Lamps	Heated Mirrors	Independent Climate Control
Intermittent Wipers	Keyless Entry	Keyless Start
LF Tires - 7/32 inch	LR Tires - 7/32 inch	Leather Steering Wheel
MP3 Radio	Master Key - 1key(s)	Motor Fuel Type - Gas
Pass-Through Rear Seat	Pass. Air Bag	Power Brakes
Power Driver & Passenger Seat	Power Driver Seat	Power Lock
Power Mirrors	Power Steering	Power Windows
Privacy Glass	RF Tires - 7/32 inch	RR Tires - 7/32 inch
Rain Sensor	Rear AC	Rear Defrost
Rear Parking Aid	Rear Reading Lamps	Rear View Mirror
Reverse Camera	Running Board	Seat Trim - Cloth
Security System	Side Airbags - Front	Spare Tire
Steering Wheel Audio Control	Stereo - AM/FM Radio	Tilt Steering Wheel
Tire Brand - Front Left - LF tire mfg Michelin	Tire Brand - Front Right - RF tire mfg Michelin	Tire Brand - Rear Left - LR tire mfg Michelin
Tire Brand - Rear Right - RR tire mfg Michelin	Tire Pressure Monitor System	Tow Hitch
Traction Control	Transmission - Automatic Transmission w/ Overdrive	Two-Wheel Drive
Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium
Wheels Rear Right - Aluminium		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown



Non Chargeable Damages



Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	3rd Row Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Multiple Scratches Light	Report	6
	Right Front Fender	Multiple Scratches Light	Report	6
	Right Rear Door	Multiple Scratches Light	Report	6
[no photo]	Oil	Low Fluid	Report	Unacceptable
[no photo]	Radio	Broken	Report	Replacement Required
	Headlining	Stained	Report	Permanent

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Hood	Chipped	Report	2
	Left Qtr Panel	Multiple Scratches Light	Report	6
	Lift Gate	Multiple Scratches Light	Report	6
	Left Front Door	Multiple Scratches Light	Report	6
	Left Front Fender	Multiple Scratches Light	Report	6
	Left Rear Door	Multiple Scratches Light	Report	6
	Roof	Multiple Scratches Light	Report	6

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.