



Approved CR

America's Auto Auction - Pensacola, Inc
6615 Mobile Highway
Pensacola, FL 32526-1264
850-972-8601/(850) 944-8482
Della.Smith@AmericasAutoAuction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
TRANSIT-350
4 Door**

Bodystyle/Series: **Vehicle XL
WAGON 148
WB**

Color: **WHITE**

Mileage: **52,139
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **1FBZX2ZM7JKB36091**

Work Order/
Stock Number: **000354843**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G433348V**

Vehicle Grade : **Grade 3.6
BATTERY
\$79 LABOR
82.50 1 HR**

Remarks: **WASH AND
VAC
APPROVED
99\$ 1 HR**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM CD	Pwr Windows	Yes
Interior - Type/Color:	Vinyl Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes

Equipment

Seats: -	Drive Type:	Rear Wheel Drive
Seat Count: -	Brakes:	Power Brakes
Additional Equipment:		
3rd Row Seat	5th Row Seat	ABS Brakes
Air Conditioning	Auxiliary Pwr Outlet	Bluetooth Connection
Brake Assist System	CD Player	Car Tire Size - RF tire size LT235/65SR16
Car Tire Size - RR tire size LT235/65SR16	Car Tire Size - LR tire size LT235/65SR16	Car Tire Size - LF tire size LT235/65SR16
Cruise Control	Cylinders - 6	Daytime Running Lights
Driver Air Bag	Empty Weight - 6034 lb	Floor Mats
Independent Climate Control	Intermittent Wipers	Keyless Entry
LF Tires - 4/32 inch	LR Tires - 9/32 inch	Leather Steering Wheel
MP3 Radio	Master Key - 1key(s)	Motor Fuel Type - Gas
Pass. Air Bag	Power Brakes	Power Lock
Power Mirrors	Power Steering	Power Windows
Privacy Glass	RF Tires - 9/32 inch	RR Tires - 8/32 inch
Rear AC	Rear Defrost	Rear View Mirror
Reverse Camera	Seat Trim - Vinyl	Side Airbags - Front
Steering Wheel Audio Control	Telematics	Tilt Steering Wheel
Tire Brand - Front Left - LF tire mfg Cooper	Tire Brand - Front Right - RF tire mfg Toyo	Tire Brand - Rear Left - LR tire mfg Cooper
Tire Brand - Rear Right - RR tire mfg Toyo	Tire Pressure Monitor System	Traction Control
Transmission - Automatic Transmission w/ Overdrive	Trip Computer	Two-Wheel Drive
Wheels Front Left - Steel	Wheels Front Right - Steel	Wheels Rear Left - Steel
Wheels Rear Right - Steel		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	3rd Row Seat	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown




Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 6	Photo Only	Estimate Only	Unknown
	Extra Photo 7	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Cargo Door	Multiple Dents/No Paint Damage	Report	4
	Right Rear Cargo Door	Multiple Dents/No Paint Damage	Report	4
	Front Bumper	Multiple Scratches Light	Refinish	5
	Roof	Multiple Scratches Light	Report	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door Panel	Worn	Report	Acceptable
	Right Front Door	Multiple Scratches Light	Report	4
	Right Front Fender	Chipped	Report	3
	Right Front Side Cargo Door	Multiple Scratches Light	Report	6
[no photo]	Battery	Inoperable	Report	Repair Required
[no photo]	Oil	Low Fluid	Report	Unacceptable
[no photo]	5th Row Seat	Aftermarket	Report	Acceptable
	Left Bed Side	Multiple Scratches Light	Report	3
	Hood	Chipped	Report	5
	Left Qtr Panel	Chipped	Remove	3
	Lift Gate Trim Panel	Aftermarket	Report	Acceptable
	Left Front Door Panel	Worn	Report	Acceptable
	Left Front Door	Multiple Scratches Light	Report	3
	Left Front Fender	Chipped	Report	2
	Right Qtr Panel	Multiple Scratches Light	Report	4

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Multiple Dents/No Paint Damage	Report	5
	Headlining	Stained	Report	Permanent

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.