



Approved
CR

IAA Syracuse
8459 Brewerton Road
Branch No 628
Cicero, NY 13039
(315) 699-2622/(315) 699-5481
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 FORD F-250**
Bodystyle/Series: **Regular Cab XL**
Color: **Black**
Mileage: **38,770 (Verified)**
Turn-in Mileage: **-**
VIN: **1FTBF2B66KED43745**
Work Order/
Stock Number: **46315509**
Customer: **GSA Fleet Vehicle Sales**
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov
Client Stock #: **G632702V**
Vehicle Grade : **Grade 2.8**
Remarks: **-**
Announcements:

- ANNOUNCEMENTS:
- Warning indicator on
- repairs may be needed
- please check OBDII report on IAA site.

Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LR 265 / 70 R 17

Car Tire Size - RF 265 / 70 R 17

Car Tire Size - LF 265 / 70 R 17

Car Tire Size - RR 265 / 70 R 17

LF Tires - 13/32 inch

LR Tires - 11/32 inch

RF Tires - 12/32 inch

RR Tires - 12/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE


Tire Model - LF - Destination M/T2

Tire Model - LR - Destination M/T2

Tire Model - RF - Destination M/T2

Tire Model - RR - Destination M/T2

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Warning Light - Engine	On	-	Unacceptable
	Fifth Wheel Trailer Hitch	Aftermarket	-	Acceptable
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Heavy Scratch	-	> 12 Inches
	Hood	Multiple Scratches Heavy	-	4

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Bed Side	Dent(S) W/ Paint Dmg	-	4 To 5 Inches
	Left Front Seat Cushion	Cut	-	1/8 To 1/2 Inch
	Left Bed Side	Dent(S) W/ Paint Dmg	-	< 1/8 Inch
	Left Front Door	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.