



Approved CR

IAA Salt Lake City
1800 South 1100 West
Branch No 342
Ogden, UT 84401-0258
(801) 399-2818/(801) 393-2325
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 FORD
F-350**
Bodystyle/Series: **Crew Cab XL**
Color: **White**
Mileage: **153,353
(Verified)**
Turn-in Mileage: **-**
VIN: **1FD8W3BT5HED72809**
Work Order/
Stock Number: **46327447**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G630954U**
Vehicle Grade : **Grade 3.4**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 75 R 17

Car Tire Size - LR 245 / 75 R 17

Car Tire Size - RR 245 / 75 R 17

Car Tire Size - RF 245 / 75 R 17

LF Tires - 6/32 inch

LR Tires - 9/32 inch

RF Tires - 6/32 inch

RR Tires - 12/32 inch

Tire Brand - Front Left - TOYO

Tire Brand - Front Right - TOYO

Tire Brand - Rear Left - TOYO

Tire Brand - Rear Right - TOYO

Tire Model - RR - M655

Tire Model - RF - M655

Tire Model - LR - M655

Tire Model - LF - M655

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Rear Metal Bumper Painted	Multiple Dents/Paint Damage	-	10 Or More
	Windshield	Multiple Chips	-	6
	Tailgate	Chipped	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.