Approved CR

IAA Portage
W10321 State Road 16
Branch No 523
Portage, WI 53901
(608) 742-1515/(608) 742-6090
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2022 CHRYSLER VOYAGER**
Bodystyle/Series:	**Van LX**
Color:	**Gray**
Mileage:	**141,298 (Verified)**
Turn-in Mileage:	-
VIN:	**2C4RC1CG4NR146637**
Work Order/ Stock Number:	**46342512**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G411893Y**
Vehicle Grade :	**Grade 3.8**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 235 / 65 R 17	Car Tire Size - LR 235 / 65 R 17	Car Tire Size - RR 235 / 65 R 17
Car Tire Size - RF 235 / 65 R 17	LF Tires - 6/32 inch	LR Tires - 8/32 inch
RF Tires - 6/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - crossover
Tire Brand - Front Right - crossover	Tire Brand - Rear Left - crossover	Tire Brand - Rear Right - crossover
Tire Model - RR - mohave cuv	Tire Model - RF - mohave cuv	Tire Model - LR - mohave cuv
Tire Model - LF - mohave cuv		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	3
	Right Front Wheel	Curb Rash	-	2 To 3 Inches
	Rear Bumper	Multiple Scratches Heavy	-	3
	Left Qtr Panel	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Lift Gate	Dent(S) W/ Paint Dmg	-	2 To 3 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.