Approved
CR

Perryopolis Auto Auction
3447 Pittsburgh Rd
PO Box 445
Perryopolis, PA 15473
724-736-4445/727-736-0466
jacob@perryautoauction.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 HYUNDAI IONIQ**
Bodystyle/Series:	**4 Door Hatch Back BLUE**
Color:	**WHITE**
Mileage:	**71,993 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**KMHC65LC2LU219808**
Work Order/ Stock Number:	**000312537**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G13-2418X**
Vehicle Grade :	**Grade 4.0**
Remarks:	-
Announcements:	• DEFICIENCIES, WHEN KNOWN, HAVE BEEN NOTED IN THE ITEM DESCRIPTION; HOWEVER, • THE ABSENCE OF ANY INDICATED DEFICIENCIES DOES NOT MEAN THERE ARE NONE
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**

Equipment

Engine:	**4-Cylinder Hybrid**	Cruise Control:	**No**
Engine Size:	**1.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	- **/GRAY**	Rear Defroster:	**No**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Additional Equipment:

Air Conditioning	Front Wheel Drive	LF Tires - 4/32 inch
LR Tires - 8/32 inch	Power Brakes	Power Steering
Power Windows	RF Tires - 4/32 inch	RR Tires - 8/32 inch
Security System	Tilt Wheel	Tire Brand - Front Left - LF TIRE MFG Kumho
Tire Brand - Front Right - RF TIRE MFG Kumho	Tire Brand - Rear Left - LR TIRE MFG Kumho	Tire Brand - Rear Right - RR TIRE MFG Kumho

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Vin Plate	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Left	Photo Only	Estimate Only	Unknown
	Photo - Right	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Front	Photo Only	Estimate Only	Unknown
	Miscellaneous	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Scraped	Repair	Unknown

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.