



Approved CR

IAA Raleigh
60 Sadisco Road
Branch No 747
Clayton, NC 27520
(919) 553-6148/(919) 553-2857
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 DODGE
CHARGER**
4 Door Sedan
Bodystyle/Series: **POLICE
AWD**
Color: **Black**
Mileage: **48,235
(Verified)**
Turn-in Mileage: -
VIN: **2C3CDXKT4KH722270**
Work Order/
Stock Number: **46400037**
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: **G110689W**
Vehicle Grade : **Grade 3.4**
Remarks: -
Announcements: -
Certification : -
Req. Prev. Repair -
Order: -



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	5.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 60 R 18

Car Tire Size - RF 225 / 60 R 18

Car Tire Size - LR 225 / 60 R 18

Car Tire Size - LF 225 / 60 R 18

LF Tires - 9/32 inch

LR Tires - 8/32 inch

RF Tires - 9/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - FALKEN

Tire Brand - Front Right - FALKEN

Tire Brand - Rear Left - FALKEN

Tire Brand - Rear Right - FALKEN

Tire Model - RR - Pro G5 CSV

Tire Model - RF - Pro G5 CSV

Tire Model - LR - Pro G5 CSV

Tire Model - LF - Pro G5 CSV

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Hood	Oxidized	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Roof	Peeling	-	> 12 Inches
	Left Front Door	Chipped	-	3
	Left Rear Door	Chipped	-	4
	Left Qtr Panel	Chipped	-	4
	Right Rear Wheel Cover	Curb Rash	-	1 To 2 Inches
	Right Front Wheel Cover	Curb Rash	-	1 To 2 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.