



Approved CR

IAA Indianapolis
3302 South Harding Street
Branch No 541
Indianapolis, IN 46217
(317) 787-3202/(317)783-0586
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
C-MAX
HYBRID**

Bodystyle/Series: **4 Door Hatch
Back SE**

Color: **Blue**

Mileage: **16,666
(Verified)**

Turn-in Mileage: **-**

VIN: **1FADP5AU5JL102055**

Work Order/
Stock Number: **46436150**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G13A4053**

Vehicle Grade : **Grade 3.9**

Remarks: **-**

Announcements:

- RIGHT FRONT STRUT RUST

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 50 R 17	Car Tire Size - LR 225 / 50 R 17	Car Tire Size - RR 225 / 50 R 17
Car Tire Size - RF 225 / 50 R 17	LF Tires - 10/32 inch	LR Tires - 10/32 inch
RF Tires - 10/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - RR - Assurance Maxlife 2	Tire Model - RF - Assurance Maxlife 2	Tire Model - LR - Assurance Maxlife 2
Tire Model - LF - Assurance Maxlife 2		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rf Strut	Rust	-	Severe Damage

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Chipped	-	5
	Rear Bumper	Chipped	-	2
	Right Rear Door	Chipped	-	2
	Right Head Lamp	Faded	-	Repair Required
	Left Head Lamp	Faded	-	Repair Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	5
	Hood	Heavy Scratch	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.