



Approved CR

IAA Indianapolis
3302 South Harding Street
Branch No 541
Indianapolis, IN 46217
(317) 787-3202/(317)783-0586
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
F-350**
Bodystyle/Series: **Regular Cab
XL**
Color: **White**
Mileage: **37,632
(Verified)**
Turn-in Mileage: **-**
VIN: **1FTRF3DT0JEC22117**
Work Order/
Stock Number: **46436067**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G63A0118**
Vehicle Grade : **Grade 3.3**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Coach	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 17

Car Tire Size - RF 245 / 75 R 17

Car Tire Size - LF 245 / 75 R 17

Car Tire Size - LR 245 / 75 R 17

LF Tires - 10/32 inch

LR Tires - 4/32 inch

RF Tires - 8/32 inch

RR Tires - 4/32 inch

Tire Brand - Front Left - MASTERCRAFT

Tire Brand - Front Right - MASTERCRAFT

Tire Brand - Rear Left - MASTERCRAFT

Tire Brand - Rear Right - MASTERCRAFT

Tire Model - LF - Courser HXT

Tire Model - LR - Courser HXT

Tire Model - RF - Courser HXT

Tire Model - RR - Courser HXT

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Running Board	Aftermarket	-	Acceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	9 To 10 Inches
	Right Front Wheel	Corrosion	-	7 To 8 Inches
	Right Qtr Flare	Chipped	-	3
	Right Rear Wheel	Curb Rash	-	> 12 Inches
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	1 To 2 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Tailgate	Chipped	-	4
	Left Rear Wheel	Curb Rash	-	9 To 10 Inches
	Left Running Board	Peeling	-	> 12 Inches
	Left Front Wheel	Corrosion	-	7 To 8 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.