Approved CR

IAA Portage
W10321 State Road 16
Branch No 523
Portage, WI 53901
(608) 742-1515/(608) 742-6090
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2021 HYUNDAI SANTA FE**
Bodystyle/Series:	**Sport Utility Vehicle SE**
Color:	**Gray**
Mileage:	**108,698 (Verified)**
Turn-in Mileage:	-
VIN:	**5NMS1DAJ3MH356100**
Work Order/ Stock Number:	**46182294**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G611610X**
Vehicle Grade :	**Grade 3.2**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2.5 L**	Pwr Steering:	**Yes**
Roof:	**Carriage**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**All Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - RR 235 / 60 R 18	Car Tire Size - RF 235 / 60 R 18	Car Tire Size - LF 235 / 60 R 18
Car Tire Size - LR 235 / 60 R 18	LF Tires - 7/32 inch	LR Tires - 7/32 inch
RF Tires - 7/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - ARGUS ADVANTA
Tire Brand - Front Right - ARGUS ADVANTA	Tire Brand - Rear Left - ARGUS ADVANTA	Tire Brand - Rear Right - ARGUS ADVANTA
Tire Model - LF - SVT-01	Tire Model - LR - SVT-01	Tire Model - RF - SVT-01
Tire Model - RR - SVT-01		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front St Back Trim Panel	Heavy Scratch	-	1 To 2 Inches
	Lr Door Panel Trim/Mld	Worn	-	Replacement Required
	Lift Gate Trim Panel	Heavy Scratch	-	> 12 Inches
	Right Interior Qtr Trim	Heavy Scratch	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Interior Qtr Trim	Heavy Scratch	-	> 12 Inches
	Right Qtr Panel	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent
	Windshield	Cracked	-	> 12 Inches
	Right Rear Door	Chipped	-	1
	Front Bumper	Chipped	-	10 Or More
	Rear Bumper Cover Upper	Heavy Scratch	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Door	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent
	Right Rear Wheel	Curb Rash	-	< 1/8 Inch
	Left Front Door	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent
	Rr Door Panel Trim/Mld	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.