



Approved CR

IAA Shreveport
4836 McGee Rd
Branch No 434
Greenwood, LA 71033
(318) 938-5108/(318) 938-5838
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016
CHEVROLET
SILVERADO
1500**

Bodystyle/Series: **Crew Cab
WT**

Color: **Gray**

Mileage: **49,859
(Verified)**

Turn-in Mileage: **-**

VIN: **3GCUKNEH2GG300894**

Work Order/
Stock Number: **46363190**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**

Client Stock #: **G622976S**

Vehicle Grade : **Grade 3.3**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	4.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 255 / 70 R 17	Car Tire Size - RF 255 / 70 R 17	Car Tire Size - LF 255 / 70 R 17
Car Tire Size - LR 255 / 70 R 17	LF Tires - 9/32 inch	LR Tires - 9/32 inch
RF Tires - 9/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - GENERAL
Tire Brand - Front Right - GENERAL	Tire Brand - Rear Left - GENERAL	Tire Brand - Rear Right - GENERAL
Tire Model - LF - Grabber Uhp	Tire Model - LR - Grabber Uhp	Tire Model - RF - Grabber Uhp
Tire Model - RR - Grabber Uhp		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Inside Bed	Multiple Dents/Paint Damage	-	10 Or More
	Tailgate Molding	Broken	-	Replacement Required
	Hood	Chipped	-	8
	Front Bumper Cover Lower	Dent(S) W/No Paint Dmg	-	< 1/8 Inch
	Left Head Lamp	Water Damage	-	Replacement Required
	Tailgate	Dent(S) W/ Paint Dmg	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.