Approved
CR

IAA El Paso
14751 Marina Ave
Branch No 420
El Paso, TX 79938
(915)852-2489/(915)852-2235
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2015 RAM 4500 CHASSIS**
Bodystyle/Series:	- **TRADESMAN/SLT**
Color:	**White**
Mileage:	**46,623 (Verified)**
Turn-in Mileage:	-
VIN:	**3C7WRKAJ5FG544911**
Work Order/ Stock Number:	**46417150**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G710519Z**
Vehicle Grade :	**Grade 2.2**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**6.4 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Leather Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Hydraulic Brakes**

Equipment

Additional Equipment:

Car Tire Size - LR 225 / 70 R 19	Car Tire Size - RR 225 / 70 R 19	Car Tire Size - RF 225 / 70 R 19
Car Tire Size - LF 225 / 70 R 19	LF Tires - 11/32 inch	LR Tires - 11/32 inch
RF Tires - 11/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - GT RADIAL
Tire Brand - Front Right - GT RADIAL	Tire Brand - Rear Left - GT RADIAL	Tire Brand - Rear Right - GT RADIAL
Tire Model - LF - GSR139	Tire Model - LR - GSR139	Tire Model - RF - GSR139
Tire Model - RR - GSR139		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	5 To 6 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Bed Side	Rust	-	> 12 Inches
	Left Front Door	Dent(S) W/ Paint Dmg	-	< 1/8 Inch
	Left Front Seat Cushion	Torn	-	1 To 2 Inches
	Steering Wheel	Worn	-	Replacement Required
	Shifter Boot	Worn	-	Replacement Required
	Tailgate	Peeling	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Head Lamp	Water Damage	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.