Approved CR

IAA Appleton
2591 S Casaloma Drive
Branch No 522
Appleton, WI 54914
(920) 734-1446/(920) 734-3603
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2016 BLUE BIRD SCHOOL BUS / TRANSIT BUS**
Bodystyle/Series:	- -
Color:	**Yellow**
Mileage:	**48,756 (Verified)**
Turn-in Mileage:	-
VIN:	**1BAKFCPA4GF314856**
Work Order/ Stock Number:	**46417180**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G320189Z**
Vehicle Grade :	**Grade 2.0**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	-	A/C:	**No**
Engine:	**6-Cylinder Diesel**	Cruise Control:	**No**
Engine Size:	**6.7 L**	Pwr Steering:	**No**
Roof:	-	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	- /-	Rear Defroster:	**No**
Airbag:	-	Tilt Steering:	**No**
Seats:	-	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	-
Additional Equipment:	-		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Mirror Housing	Broken	-	Replacement Required
	Left Front Tire	Missing	-	Replacement Required
	Left Side Panel	Rust	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Grille	Peeling	-	> 12 Inches
	Rear Metal Bumper Painted	Rust	-	> 12 Inches
	Hood	Peeling	-	> 12 Inches
	Front Metal Bumper Painted	Heavy Scratch	-	4 To 5 Inches
	Overall Vehicle	De-Identify	-	Removal Required
	Left Rear Tire	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Tire	Worn	-	Replacement Required
	Right Front Tire	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.