



Approved CR

IAA Santa Clarita  
14320 Soledad Canyon Rd  
Branch No 128  
Santa Clarita, CA 91387  
(818) 655-0279/(224) 348-4123  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 JEEP  
GRAND  
CHEROKEE**  
Bodystyle/Series: **Sport Utility  
Vehicle  
LAREDO  
4X2**  
Color: **Navy**  
Mileage: **80,438  
(Verified)**  
Turn-in Mileage: **-**  
VIN: **1C4RJEAG4HC855811**  
Work Order/  
Stock Number: **46404709**  
Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalessupport@gsa.gov**  
Client Stock #: **G420517U**  
Vehicle Grade : **Grade 3.6**  
Remarks: **-**  
Announcements: **-**  
Certification : **-**  
Req. Prev. Repair **-**  
Order:



Drivable: Yes

### Equipment

|                        |                               |                 |                         |
|------------------------|-------------------------------|-----------------|-------------------------|
| Transmission:          | <b>Automatic Transmission</b> | A/C:            | <b>No</b>               |
| Engine:                | <b>6-Cylinder Flex Fuel</b>   | Cruise Control: | <b>Yes</b>              |
| Engine Size:           | <b>3.6 L</b>                  | Pwr Steering:   | <b>Yes</b>              |
| Roof:                  | <b>Hard Top</b>               | Pwr Locks:      | <b>Yes</b>              |
| Radio:                 | <b>-</b>                      | Pwr Windows     | <b>Yes</b>              |
| Interior - Type/Color: | <b>Cloth Interior /-</b>      | Rear Defroster: | <b>Yes</b>              |
| Airbag:                | <b>Driver Side Air Bag</b>    | Tilt Steering:  | <b>Yes</b>              |
| Seats:                 | <b>Buckets</b>                | Drive Type:     | <b>Rear Wheel Drive</b> |
| Seat Count:            | <b>-</b>                      | Brakes:         | <b>Disc</b>             |

## Equipment

### Additional Equipment:

Car Tire Size - RR 245 / 70 R 17

Car Tire Size - RF 245 / 70 R 17

Car Tire Size - LF 245 / 70 R 17

Car Tire Size - LR 245 / 70 R 17

LF Tires - 5/32 inch

LR Tires - 6/32 inch

RF Tires - 9/32 inch

RR Tires - 7/32 inch

Tire Brand - Front Left - KUMHO

Tire Brand - Front Right - KUMHO

Tire Brand - Rear Left - KUMHO

Tire Brand - Rear Right - KUMHO

Tire Model - LF - Crugen HT51

Tire Model - LR - Crugen HT51

Tire Model - RF - Crugen HT51

Tire Model - RR - Crugen HT51

## Non Chargeable Damages

| Photo                                                                               | Item                   | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|------------------------|------------|--------|----------|
|    | Photo - Vin/Id Sticker | Photo Only | -      | -        |
|    | Engine                 | Photo Only | -      | -        |
|   | Keys                   | Photo Only | -      | -        |
|  | Front Cover Center     | Photo Only | -      | -        |
|  | Right Side Panel       | Photo Only | -      | -        |
|  | Left Side Panel        | Photo Only | -      | -        |
|  | Instrument Panel       | Photo Only | -      | -        |
|  | Rear Bumper            | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
|    | Extra Photo 2           | Photo Only | -      | -        |
|    | Extra Photo 3           | Photo Only | -      | -        |
|    | Right Front Fender      | Photo Only | -      | -        |
|    | Extra Photo 4           | Photo Only | -      | -        |
|    | Extra Photo 5           | Photo Only | -      | -        |
|   | Extra Photo 6           | Photo Only | -      | -        |
|  | Left Front Fender       | Photo Only | -      | -        |
|  | Left Rear Bumper/Cover  | Photo Only | -      | -        |
|  | Right Rear Bumper/Cover | Photo Only | -      | -        |
|  | Photo - Dash            | Photo Only | -      | -        |
|  | Extra Photo 1           | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                             | Item       | Damage     | Action | Severity |
|-----------------------------------------------------------------------------------|------------|------------|--------|----------|
|  | Odometer   | Photo Only | -      | -        |
|  | Rear Seats | Photo Only | -      | -        |

### Chargeable Damages

| Photo                                                                               | Item              | Damage        | Action | Severity        |
|-------------------------------------------------------------------------------------|-------------------|---------------|--------|-----------------|
|    | Left Front Door   | Chipped       | -      | 5               |
|   | Left Front Fender | Heavy Scratch | -      | 1/2 To 1 Inch   |
|  | Front Bumper      | Misaligned    | -      | Repair Required |
|  | Hood              | Chipped       | -      | 10 Or More      |
|  | Rear Bumper       | Heavy Scratch | -      | > 12 Inches     |

| Chargeable Damages                                                                |                |                          |        |             |
|-----------------------------------------------------------------------------------|----------------|--------------------------|--------|-------------|
| Photo                                                                             | Item           | Damage                   | Action | Severity    |
|  | Left Qtr Panel | Chipped                  | -      | 2           |
|  | Left Rear Door | Multiple Scratches Heavy | -      | 3           |
|  | Front Bumper   | Heavy Scratch            | -      | > 12 Inches |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.