



Approved CR

IAA Las Vegas
3225 South Hollywood Blvd
Branch No 152
Las Vegas, NV 89122
(702) 565-8795/(702) 564-6553
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018
CHEVROLET
SILVERADO
2500HD**

Bodystyle/Series: **Crew Cab
WT**

Color: **Dark Blue**

Mileage: **54,753
(Verified)**

Turn-in Mileage: **-**

VIN: **1GC1KUEG1JF230611**

Work Order/
Stock Number: **46328164**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G630605V**

Vehicle Grade : **Grade 2.4**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Air Brakes

Equipment


Additional Equipment:

Car Tire Size - LF 265 / 70 R 17	Car Tire Size - LR 265 / 70 R 17	Car Tire Size - RR 265 / 70 R 17
Car Tire Size - RF 265 / 70 R 17	LF Tires - 11/32 inch	LR Tires - 10/32 inch
RF Tires - 11/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - SUMMIT
Tire Brand - Front Right - SUMMIT	Tire Brand - Rear Left - SUMMIT	Tire Brand - Rear Right - SUMMIT
Tire Model - RR - Trail Climber HT03	Tire Model - RF - Trail Climber HT03	Tire Model - LR - Trail Climber HT03
Tire Model - LF - Trail Climber HT03		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Cargo Shelf	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Roof Luggage Rack	Aftermarket	-	Acceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Scuffed	-	> 12 Inches
	Right Front Seat Cushion	Torn	-	5 To 6 Inches
	Right Front Seat Back	Stained	-	Permanent

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Seat Cushion	Torn	-	7 To 8 Inches
	Steering Wheel	Gouged	-	1/2 To 1 Inch
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Right Front Fender	Chipped	-	3
	Tailgate	Multiple Dents/Paint Damage	-	5
	Right Front Door	Chipped	-	4

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Door	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Right Bed Side	Chipped	-	3
	Right Rear Wheel	Curb Rash	-	1 To 2 Inches
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	> 12 Inches
	Left Bed Side	Multiple Dents/Paint Damage	-	2
	Left Rocker Panel	Scraped	-	4 To 5 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Fender	Chipped	-	2
	Left Front Wheel	Curb Rash	-	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.