Approved CR

IAA Central NJ
426 Texas Road
Branch No 614
Morganville, NJ 07751
(732) 591-8173/(732) 591-8393
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2021 NISSAN MAXIMA**
Bodystyle/Series:	**4 Door Sedan SV XTRONIC CVT**
Color:	**Black**
Mileage:	**93,029 (Verified)**
Turn-in Mileage:	-
VIN:	**1N4AA6CV5MC514092**
Work Order/ Stock Number:	**46474004**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G110222Y**
Vehicle Grade :	**Grade 3.4**
Remarks:	-
Announcements:	• Warning light on repairs may be needed check IAA OBD11 REPORT FOR DETAILS
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Continuously Variable Transmission**	A/C:	**No**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3.5 L**	Pwr Steering:	**Yes**
Roof:	**Carriage**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Synthetic Leather /BLACK**	Rear Defroster:	**Yes**

Equipment

Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Additional Equipment:

Car Tire Size - RR 245 / 45 R 18	Car Tire Size - RF 245 / 45 R 18	Car Tire Size - LF 245 / 45 R 18
Car Tire Size - LR 245 / 45 R 18	LF Tires - 9/32 inch	LR Tires - 9/32 inch
RF Tires - 9/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - LF - Eagle RS-A	Tire Model - LR - Eagle RS-A	Tire Model - RF - Eagle RS-A
Tire Model - RR - Eagle RS-A		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Multiple Scratches Heavy	-	2
	Front Bumper	Chipped	-	4
	Right Front Fender	Multiple Scratches Heavy	-	3
	Right Front Door	Chipped	-	2
	Right Front Wheel	Curb Rash	-	1 To 2 Inches
	Right Qtr Panel	Multiple Scratches Heavy	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Curb Rash	-	2 To 3 Inches
	Left Rear Wheel	Curb Rash	-	2 To 3 Inches
	Left Front Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Left Front Wheel	Curb Rash	-	2 To 3 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.