Approved CR

IAA Kansas City
2663 S 88th Street
Branch No 527
Kansas City, KS 66111
(913) 422-9303/(913) 422-7421
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2016 CHEVROLET EXPRESS 3500**
Bodystyle/Series:	**- LT**
Color:	**Silver**
Mileage:	**62,895 (Verified)**
Turn-in Mileage:	-
VIN:	**1GAZGPFF2G1273770**
Work Order/ Stock Number:	**45693734**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G431172S**
Vehicle Grade :	**Grade 3.3**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment


Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**4.8 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**5th**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - LR 245 / 75 R 16	Car Tire Size - RR 245 / 75 R 16	Car Tire Size - LF 245 / 75 R 16
Car Tire Size - RF 245 / 75 R 16	LF Tires - 14/32 inch	LR Tires - 14/32 inch
RF Tires - 9/32 inch	RR Tires - 13/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - LF - Wrangler Workhorse HT	Tire Model - LR - Wrangler Workhorse HT	Tire Model - RF - Wrangler HT
Tire Model - RR - Wrangler Workhorse HT		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Corrosion	-	2 To 3 Inches
	Left Rear Wheel	Corrosion	-	2 To 3 Inches
	Left Front Wheel	Corrosion	-	2 To 3 Inches
	Left Front Seat Bolster	Torn	-	3 To 4 Inches
	Steering Wheel	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	1/2 To 1 Inch
	Hood	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Right Front Wheel	Corrosion	-	2 To 3 Inches
	Left Dutch Cargo Door	Multiple Dents/Paint Damage	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.