



Approved
CR

IAA Anchorage
1446 W Mystery Ave
Branch No 372
Wasilla, AK 99654
(907)312-5580/(907)312-5680
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 RAM
1500**

Bodystyle/Series: **-
TRADESMAN**

Color: **Gray**

Mileage: **28,255
(Verified)**

Turn-in Mileage: **-**

VIN: **1C6RR7FG6GS377318**

Work Order/
Stock Number: **46287235**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G624387S**

Vehicle Grade : **Grade 3.7**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment


Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 265 / 70 R 17	Car Tire Size - LR 265 / 70 R 17	Car Tire Size - RR 265 / 70 R 17
Car Tire Size - RF 265 / 70 R 17	LF Tires - 9/32 inch	LR Tires - 8/32 inch
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - RR - Wrangler SR-A	Tire Model - RF - Wrangler SR-A	Tire Model - LR - Wrangler SR-A
Tire Model - LF - Wrangler SR-A		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Chipped	-	10 Or More
	Inside Bed	Heavy Scratch	-	> 12 Inches
	Windshield	Multiple Chips	-	3
	Left Front Fender	Chipped	-	1
	Left Front Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	4 To 5 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.