Approved CR

IAA El Paso
14751 Marina Ave
Branch No 420
El Paso, TX 79938
(915)852-2489/(915)852-2235
WHOLESALE ASSESSMENT ONLY




| | |
|---|---|
| Make/Model: | **2018 FORD TRANSIT-350** |
| Bodystyle/Series: | **Wagon XL** |
| Color: | **White** |
| Mileage: | **49,339 (Verified)** |
| Turn-in Mileage: | - |
| VIN: | **1FBZX2ZM5JKB36039** |
| Work Order/ Stock Number: | **45981737** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | **G433224V** |
| Vehicle Grade : | **Grade 3.8** |
| Remarks: | - |
| Announcements: | - |
| Certification : | - |
| Req. Prev. Repair Order: | - |

Drivable: Yes

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Automatic Transmission** | A/C: | **No** |
| Engine: | **6-Cylinder Gas** | Cruise Control: | **Yes** |
| Engine Size: | **3.7 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **Yes** |
| Radio: | - | Pwr Windows | **Yes** |
| Interior - Type/Color: | **Cloth/Vinyl /BLACK** | Rear Defroster: | **Yes** |
| Airbag: | **Driver Side Air Bag** | Tilt Steering: | **Yes** |
| Seats: | **Buckets** | Drive Type: | **Rear Wheel Drive** |
| Seat Count: | - | Brakes: | **Hydraulic Brakes** |

## Equipment

Additional Equipment:

| | | |
|---|---|---|
| Car Tire Size - RR 235 / 65 R 16 | Car Tire Size - RF 235 / 65 R 16 | Car Tire Size - LF 235 / 65 R 16 |
| Car Tire Size - LR 235 / 65 R 16 | LF Tires - 11/32 inch | LR Tires - 11/32 inch |
| RF Tires - 11/32 inch | RR Tires - 11/32 inch | Tire Brand - Front Left - FIRESTONE |
| Tire Brand - Front Right - FIRESTONE | Tire Brand - Rear Left - FIRESTONE | Tire Brand - Rear Right - FIRESTONE |
| Tire Model - LF - Transforce CV | Tire Model - LR - Transforce CV | Tire Model - RF - Transforce CV |
| Tire Model - RR - Transforce CV | | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Rear Seats | Photo Only | - | - |
|  | Photo - Vin/Id Sticker | Photo Only | - | - |
|  | Engine | Photo Only | - | - |
|  | Keys | Photo Only | - | - |
|  | Front Cover Center | Photo Only | - | - |
|  | Right Side Panel | Photo Only | - | - |
|  | Left Side Panel | Photo Only | - | - |
|  | Instrument Panel | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Rear Bumper | Photo Only | - | - |
|  | Right Front Fender | Photo Only | - | - |
|  | Left Front Fender | Photo Only | - | - |
|  | Left Rear Bumper/Cover | Photo Only | - | - |
|  | Right Rear Bumper/Cover | Photo Only | - | - |
|  | Photo - Dash | Photo Only | - | - |
|  | Extra Photo 1 | Photo Only | - | - |
|  | Odometer | Photo Only | - | - |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Qtr Panel | Dent(S) W/No Paint Dmg | - | > 12 Inches |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Left Fuel Door | Missing | - | Replacement Required |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.