



Approved CR

Dealers Auto Auction of Little Rock
4600 S University Ave
Little Rock , AR 72204
501-904-9988
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016
CHEVROLET
EXPRESS
PASSENGER**

Bodystyle/Series: **Van LT
WAGON
EXT**

Color: **GRAY**

Mileage: **70,366
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **1GAZGPGF5G1316913**

Work Order/
Stock Number: **000072544**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G432749S**

Vehicle Grade : **Grade 3.6**

Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment


Additional Equipment:

3rd Row Seat	ABS Brakes	Air Conditioning
Auxiliary Pwr Outlet	Bluetooth Connection	Car Tire Size - RR tire size LT245/75R16E
Car Tire Size - RF tire size LT245/75R16E	Car Tire Size - LR tire size LT245/75R16E	Car Tire Size - LF tire size LT245/75R16E
Cruise Control	Cylinders - 8	Daytime Running Lights
Driver Air Bag	Engine Immobilizer	Floor Mats
Front Reading Lamps	Intermittent Wipers	Keyless Entry
LF Tires - 11/32 inch	LR Tires - 11/32 inch	Leather Steering Wheel
MP3 Radio	Master Key - 2key(s)	Motor Fuel Type - Other
Pass-Through Rear Seat	Pass. Air Bag	Power Brakes
Power Lock	Power Steering	Power Windows
Privacy Glass	RF Tires - 11/32 inch	RR Tires - 11/32 inch
Rear AC	Rear View Mirror	Seat Trim - Cloth
Side Airbags - Front	Spare Tire	Steering Wheel Audio Control
Stereo - AM/FM Radio	Tilt Steering Wheel	Tilt Wheel
Tire Brand - Front Left - Hood	Tire Brand - Front Left - LF tire mfg Other	Tire Brand - Front Right - RF tire mfg Other
Tire Brand - Rear Left - LR tire mfg Other	Tire Brand - Rear Right - RR tire mfg Other	Tire Pressure Monitor System
Traction Control	Transmission - Automatic Transmission w/ Overdrive	Trip Computer
Two-Wheel Drive	Wheels Front Left - Steel	Wheels Front Right - Steel
Wheels Rear Left - Steel	Wheels Rear Right - Steel	

Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Door Panels	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Hood	Photo Only	Estimate Only	Unknown
	Left Qtr Panel	Photo Only	Estimate Only	Unknown
	Right Qtr Panel	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	3rd Row Seat	Photo Only	Estimate Only	Unknown

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Door	Multiple Dents/Paint Damage	Repair	3
	Right Front Door	Enviro Paint Damage	Repair	11 To 12 Inches
	Right Swing Door	Multiple Scratches Light	Touch Up	5
	Right Bed Side	Multiple Scratches Light	Touch Up	3
	Left Front Door	Enviro Paint Damage	Repair	> 12 Inches
	Cab - Left	Multiple Scratches Light	Wet Sand	4
	Left Rear Cargo Door	Dent(S) W/No Paint Dmg	Report	2 To 3 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.