



Approved CR

IAA Portland
4415 NE 158th Avenue
Branch No 308
Portland, OR 97230
(503) 253-1500/(503) 253-9359
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
F-250**
Bodystyle/Series: **Extended Cab
XL**
Color: **Silver**
Mileage: **81,122
(Verified)**
Turn-in Mileage: **-**
VIN: **1FD7X2B62JEC69740**
Work Order/
Stock Number: **46393190**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G632407V**
Vehicle Grade : **Grade 1.8**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	No
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Vinyl Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 75 R 17

Car Tire Size - LR 245 / 75 R 17

Car Tire Size - RR 245 / 75 R 17

Car Tire Size - RF 245 / 75 R 17

LF Tires - 10/32 inch

LR Tires - 9/32 inch

RF Tires - 10/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - TOYO

Tire Brand - Front Right - TOYO

Tire Brand - Rear Left - TOYO

Tire Brand - Rear Right - TOYO

Tire Model - RR - M-55

Tire Model - RF - M-55

Tire Model - LR - M-55

Tire Model - LF - M-55

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Right Tool Box	Aftermarket	-	Acceptable
	Pickup Bed	Aftermarket	-	Acceptable
	Left Rear Rail	Previous Repair	-	Acceptable
	Right Rear Rail	Previous Repair	-	Acceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Tool Box	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Chipped	-	10 Or More
	Front Valance	Cracked	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	2 To 3 Inches
	Right Bed Side	Multiple Scratches Heavy	-	3
	Right Rear Wheel	Curb Rash	-	1 To 2 Inches
	Rear Metal Bumper Painted	Multiple Scratches Heavy	-	2
	Tailgate	Multiple Scratches Heavy	-	6
	Left Bed Side	Dent(S) W/ Paint Dmg	-	1 To 2 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Curb Rash	-	2 To 3 Inches
	Left Front Door	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Left Front Wheel	Curb Rash	-	> 12 Inches
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Hood	Chipped	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.