



Approved CR

IAA San Diego
2380 Britannia Blvd
Branch No 116
San Diego, CA 92154
(619) 710-2866/(619) 710-2878
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019
CHEVROLET
EXPRESS
3500**

Bodystyle/Series: **Van LS**

Color: **White**

Mileage: **37,360
(Verified)**

Turn-in Mileage: **-**

VIN: **1GAZGNFG2K1326716**

Work Order/
Stock Number: **46262506**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G432085W**

Vehicle Grade : **Grade 4.0**

Remarks: **-**

Announcements:

**• WARNING
INDICATOR
LIGHT ON
(SEE IAA
CONDITION
REPORT
FOR
DETAILS) R**

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes

Equipment

Seats:	5th	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Additional Equipment:

Car Tire Size - RR 245 / 75 R 16	Car Tire Size - RF 245 / 75 R 16	Car Tire Size - LF 245 / 75 R 16
Car Tire Size - LR 245 / 75 R 16	LF Tires - 13/32 inch	LR Tires - 10/32 inch
RF Tires - 13/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - FIRESTONE
Tire Model - LF - Destination X/T	Tire Model - LR - Destination X/T	Tire Model - RF - Destination X/T
Tire Model - RR - Destination X/T		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Tire Pressure	On	-	Unacceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	> 12 Inches
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Front Wheel	Corrosion	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.