



Approved CR

IAA Santa Clarita
14320 Soledad Canyon Rd
Branch No 128
Santa Clarita, CA 91387
(818) 655-0279/(224) 348-4123
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 FORD
TRANSIT-150**
Bodystyle/Series: **Wagon XL**
Color: **White**
Mileage: **21,151
(Verified)**
Turn-in Mileage: **-**
VIN: **1FMZK1ZMXGKB41911**
Work Order/
Stock Number: **46419621**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G422417S**
Vehicle Grade : **Grade 4.0**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 235 / 65 R 16	Car Tire Size - LF 235 / 65 R 16	Car Tire Size - RF 235 / 65 R 16
Car Tire Size - LR 235 / 65 R 16	LF Tires - 9/32 inch	LR Tires - 8/32 inch
RF Tires - 9/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - OTANI
Tire Brand - Front Right - OTANI	Tire Brand - Rear Left - OTANI	Tire Brand - Rear Right - OTANI
Tire Model - RR - MK2000	Tire Model - RF - MK2000	Tire Model - LR - MK2000
Tire Model - LF - MK2000		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
-------	------	--------	--------	----------

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Qtr Panel	Multiple Scratches Heavy	-	2
	Right Front Side Cargo Door	Multiple Scratches Heavy	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.