Approved CR

IAA Fontana
9951 Banana Ave
Branch No 132
Fontana, CA 92335
(909)355-9400/(909)822-9311
WHOLESALE ASSESSMENT ONLY



| | |
|---|---|
| Make/Model: | **2018 JEEP CHEROKEE** |
| Bodystyle/Series: | **Sport Utility Vehicle LATITUDE 4X4** |
| Color: | **White** |
| Mileage: | **34,247 (Verified)** |
| Turn-in Mileage: | - |
| VIN: | **1C4PJMCB9JD531871** |
| Work Order/ Stock Number: | **46452416** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | **G612070U** |
| Vehicle Grade : | **Grade 4.1** |
| Remarks: | - |
| Announcements: | - |
| Certification : | - |
| Req. Prev. Repair Order: | - |

Drivable: Yes

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Automatic Transmission** | A/C: | **No** |
| Engine: | **4-Cylinder Gas** | Cruise Control: | **Yes** |
| Engine Size: | **2.4 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **Yes** |
| Radio: | - | Pwr Windows | **Yes** |
| Interior - Type/Color: | **Cloth Interior /BLACK** | Rear Defroster: | **Yes** |
| Airbag: | **Driver Side Air Bag** | Tilt Steering: | **Yes** |
| Seats: | **3rd** | Drive Type: | **4-Wheel Drive** |
| Seat Count: | - | Brakes: | **Disc** |

## Equipment

Additional Equipment:

| | | |
|---|---|---|
| Car Tire Size - LF 225 / 65 R 17 | Car Tire Size - LR 225 / 65 R 17 | Car Tire Size - RR 225 / 65 R 17 |
| Car Tire Size - RF 225 / 65 R 17 | LF Tires - 6/32 inch | LR Tires - 5/32 inch |
| RF Tires - 5/32 inch | RR Tires - 6/32 inch | Tire Brand - Front Left - FIRESTONE |
| Tire Brand - Front Right - FIRESTONE | Tire Brand - Rear Left - FIRESTONE | Tire Brand - Rear Right - FIRESTONE |
| Tire Model - RR - Destination Le | Tire Model - RF - Destination Le | Tire Model - LR - Destination Le |
| Tire Model - LF - Destination Le | | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Rear Bumper/Cover | Photo Only | - | - |
|  | Photo - Dash | Photo Only | - | - |
|  | Extra Photo 1 | Photo Only | - | - |
|  | Odometer | Photo Only | - | - |
|  | Left Rear Bumper/Cover | Photo Only | - | - |
|  | Left Front Fender | Photo Only | - | - |
|  | Right Front Fender | Photo Only | - | - |
|  | Extra Photo 2 | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Rear Bumper | Photo Only | - | - |
|  | Instrument Panel | Photo Only | - | - |
|  | Left Side Panel | Photo Only | - | - |
|  | Right Side Panel | Photo Only | - | - |
|  | Front Cover Center | Photo Only | - | - |
|  | Keys | Photo Only | - | - |
|  | Engine | Photo Only | - | - |
|  | Photo - Vin/Id Sticker | Photo Only | - | - |
|  | Rear Seats | Photo Only | - | - |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Front Bumper | Heavy Scratch | - | 4 To 5 Inches |
|  | Windshield | Star In Glass | - | 1/8 To 1/2 Inch |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.