Approved
CR

IAA Santa Clarita
14320 Soledad Canyon Rd
Branch No 128
Santa Clarita, CA 91387
(818) 655-0279/(224) 348-4123
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2017 FORD F-350 CHASSIS**
Bodystyle/Series:	**Extended Cab XL**
Color:	**White**
Mileage:	**65,829 (Verified)**
Turn-in Mileage:	-
VIN:	**1FD8X3HT8HEF22996**
Work Order/ Stock Number:	**46409371**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G633214U**
Vehicle Grade :	**Grade 3.7**
Remarks:	-
Announcements:	• SEE IAA CONDITION REPORT FOR MORE INFORMATION. REPAIRS MAYBE NEEDED
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Diesel**	Cruise Control:	**Yes**
Engine Size:	**6.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**

Equipment

Seat Count: -

Brakes: **Disc**



Additional Equipment:

Car Tire Size - LR 285 / 70 R 17	Car Tire Size - RR 285 / 70 R 17	Car Tire Size - RF 285 / 70 R 17
Car Tire Size - LF 285 / 70 R 17	LF Tires - 16/32 inch	LR Tires - 15/32 inch
RF Tires - 16/32 inch	RR Tires - 15/32 inch	Tire Brand - Front Left - FALKEN
Tire Brand - Front Right - FALKEN	Tire Brand - Rear Left - FALKEN	Tire Brand - Rear Right - FALKEN
Tire Model - LF - Wildpeak A/T4W	Tire Model - LR - Wildpeak A/T4W	Tire Model - RF - Wildpeak A/T4W
Tire Model - RR - Wildpeak A/T4W		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Right Front Fender	Photo Only	-	-
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Door Applique	Broken	-	Replacement Required
	Windshield	Broken	-	Replacement Required
	Right Front Wheel	Rust	-	Repair Required
	Overall Vehicle	De-Identify	-	Removal Required
	Left Front Door Applique	Broken	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.