Approved CR

IAA Colorado Springs
8500 Import Ct
Branch No 377
Colorado Springs, CO 80925
(719) 755-0862/(719) 715-0988
mgr-coloradosprings@iaai.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2016 CHEVROLET SILVERADO 2500HD**
Bodystyle/Series:	**Crew Cab WORK TRUCK**
Color:	**Gray**
Mileage:	**79,876 (Verified)**
Turn-in Mileage:	-
VIN:	**1GC1KUEG1GF192662**
Work Order/ Stock Number:	**45693362**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G63-0332W**
Vehicle Grade :	**Grade 0.8**
Remarks:	-
Announcements:	• HAIL DAMAGE
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment


Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 265 / 70 R 17	Car Tire Size - RF 265 / 70 R 17	Car Tire Size - LF 265 / 70 R 17
Car Tire Size - LR 265 / 70 R 17	LF Tires - 14/32 inch	LR Tires - 14/32 inch
RF Tires - 14/32 inch	RR Tires - 14/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - LF - Wrangler Duratrac RT	Tire Model - LR - Wrangler Duratrac RT	Tire Model - RF - Wrangler Duratrac RT
Tire Model - RR - Wrangler Duratrac RT		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Mirror Housing	Broken	-	Replacement Required
	Right Front Fender	Hail Damage	-	10 Or More
	Right Front Door	Hail Damage	-	3
	Right Rear Door	Hail Damage	-	3
	Right Rocker Panel	Heavy Scratch	-	5 To 6 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Peeling	-	> 12 Inches
	Right Rear Door Applique	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Right Bed Side	Hail Damage	-	10 Or More
	Right Cab Side	Hail Damage	-	3
	Right Rear Center Cap	Broken	-	Replacement Required
	Tailgate	Hail Damage	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Bed Side	Hail Damage	-	3
	Cab - Left	Hail Damage	-	3
	Right Rear Wheel	Peeling	-	> 12 Inches
	Left Rear Wheel	Peeling	-	> 12 Inches
	Left Rear Door	Hail Damage	-	10 Or More
	Front Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Peeling	-	> 12 Inches
	Left Front Door Panel	Stained	-	Permanent
	Steering Wheel	Worn	-	Replacement Required
	Dash Cluster Lens	Heavy Scratch	-	Replacement Required
	Tailgate Molding	Heavy Scratch	-	1 To 2 Inches
	Roof	Hail Damage	-	10 Or More

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Drip Rail	Hail Damage	-	10 Or More
	Right Drip Rail	Hail Damage	-	10 Or More
	Left Front Seat Back	Torn	-	4 To 5 Inches
	Console Cover	Torn	-	3 To 4 Inches
	Left Front Fender	Hail Damage	-	3
	Hood	Hail Damage	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.