Approved CR

Rawls Auto Auction Inc.
2818 Pond Branch Rd.
Leesville, SC 29070
(803) 859-5111/(803) 859-0517
wendyc@rawlsautoauction.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2016 FORD F-59 COMMERCIAL STRIPPED CHASS**
Bodystyle/Series:	**2 Door Vehicle STRIPPED CHASSIS 178" DRW**
Color:	**WHITE**
Mileage:	**28,317 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**1F65F5KY1G0A00431**
Work Order/ Stock Number:	**000381699**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G71A0554**
Vehicle Grade :	**Grade 3.9**
Remarks:	-
Announcements:	• BATTERY INOP • NEEDS BOOSTING
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**10-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**6.8 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**No**
Radio:	**AM/FM Radio**	Pwr Windows	**No**

Equipment

Interior - Type/Color:	**Vinyl Interior /BLACK**	Rear Defroster:	**No**
Airbag:	-	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Additional Equipment:

ABS Brakes	Air Conditioning	Car Tire Size - LR tire size LT225/70SR19.5
Car Tire Size - RF tire size LT225/70SR19.5	Car Tire Size - LF tire size LT225/70SR19.5	Car Tire Size - RR tire size LT225/70SR19.5
Cruise Control	Cylinders - 10	Daytime Running Lights
Dual Rear Wheels	Empty Weight - 5945 lb	Independent Climate Control
LF Tires - 12/32 inch	LR Tires - 14/32 inch	Master Key - 2key(s)
Motor Fuel Type - Gas	OK Odor	Power Brakes
Power Steering	RF Tires - 12/32 inch	RR Tires - 14/32 inch
Rear View Mirror	Seat Trim - Vinyl	Stereo - AM/FM Radio
Tilt Steering Wheel	Tilt Wheel	Tire Brand - Front Left - LF tire mfg Firestone
Tire Brand - Front Right - RF tire mfg Firestone	Tire Brand - Rear Left - LR tire mfg Firestone	Tire Brand - Rear Right - RR tire mfg Firestone
Transmission - Automatic Transmission w/ Overdrive	Two-Wheel Drive	Wheels Front Left - Steel
Wheels Front Right - Steel	Wheels Rear Left - Steel	Wheels Rear Right - Steel

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Dash Cluster Lens	Cracked	Replace	Replacement Required
	Front Bumper	Multiple Scratches Heavy	Repair	3
	Left Front Seat	Torn	Replace	7 To 8 Inches
	Rear Bumper	Multiple Scratches Heavy	Repair	10 Or More
[no photo]	Battery	Inoperable	Replace	Repair Required
[no photo]	Hood	Chipped	Touch Up	10 Or More
[no photo]	Left Rear Wheel	Rust	Refinish	Repair Required
[no photo]	Overall Vehicle	Multiple Scratches Light	Wet Sand	10 Or More
[no photo]	Right Front Wheel	Rust	Refinish	Repair Required
[no photo]	Right Rear Wheel	Rust	Refinish	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE

SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.