Approved
CR

Orlando Auto Auction
4636 W. Colonial Dr
Orlando, FL 32808
(407) 299-3904/(407) 294-6982
david.orlandoautoauction@gmail.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 FORD TRANSIT-350**
Bodystyle/Series:	**3 Door Wagon XL**
Color:	**WHITE**
Mileage:	**25,525 (Digital)**
Turn-in Mileage:	-
VIN:	**1FBZX2ZM4JKB42799**
Work Order/ Stock Number:	**0318668**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G431838V**
Vehicle Grade :	**Grade 4.2**
Remarks:	-
Announcements:	• DEFICIENCIES, WHEN KNOWN, HAVE BEEN NOTED IN THE • ITEM DESCRIPTION; HOWEVER, THE ABSENCE OF ANY • INDICATED DEFICIENCIES DOES NOT MEAN THERE ARE • NONE.
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission w/ Overdrive**	A/C:	**Yes**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**

Equipment

Engine Size:	**3.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**CD Only**	Pwr Windows	**Yes**
Interior - Type/Color:	**- /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Buckets**	Drive Type:	**Rear Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Additional Equipment:

3rd Row Seat	Auxiliary Audio Input	Auxiliary Pwr Outlet
Backup camera and monitor	Bluetooth Connection	Brake Assist System
Car LF Tires - 8/32 inch	Car LR Tires - 5/32 inch	Car RF Tires - 10/32 inch
Car RR Tires - 5/32 inch	Car Tire Size - LF: LT235/65SR16 LR: LT235/65SR16 RF: LT235/65SR16 RR: LT235/65SR16	Cylinders - 6
Daytime Running Lights	Driver Illuminated Vanity Mirr	Driver Vanity Mirror
Electronic Stability Control	Front Head Air Bag	Ignition Key - 1key(s)
Independent Climate Control	Intermittent Wipers	Keyless Entry - Left
LF Tires - 8/32 inch	LR Tires - 5/32 inch	Leather Steering Wheel
MP3 Radio	Misc. Special Features - Passenger Third Door, Airbag Disconnect Switch	Pass. Air Bag
Passenger Air Bag Sensor	Passenger Illuminated Vanity M	Passenger Vanity Mirror
Power Mirrors	Privacy Glass	RF Tires - 10/32 inch
RR Tires - 5/32 inch	Rear AC	Rear Bench Seat
Rear Head Air Bag	Side Airbags - Front	Smart Device Integration
Steering Wheel Audio Control	Telematics	Tilt Steering Wheel
Tire Brand - Front Left - CONTINENTAL	Tire Brand - Front Right - TOYO	Tire Brand - Rear Left - CONTINENTAL
Tire Brand - Rear Right - CONTINENTAL	Tire LF - 8/32 inch	Tire Pressure Monitor System
Tire RF - 10/32 inch	Tire Size - LF: LT235/65SR16 LR: LT235/65SR16 RF: LT235/65SR16 RR: LT235/65SR16	Tire Size - LF: LT235/65SR16 LR: LT235/65SR16 RF: LT235/65SR16 RR: LT235/65SR16
Transmission - Automatic Transmission w/ Overdrive	Trip Computer	Wheels Front Left - Steel
Wheels Front Right - Steel	Wheels Rear Left - Steel	Wheels Rear Right - Steel
WiFi Hotspot		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 9	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rocker Panel Molding	Missing	Replace	Replacement Required
	Right Rear Cargo Door	Multiple Dents/No Paint Damage	Repair	3
	Rear Bumper/Cover	Gouged	Repair	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.