Approved CR

IAA Elkton
183 Zeitler Rd
Branch No 786
Elkton, MD 21921
(410) 695-4477
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 FORD TRANSIT CONNECT**
Bodystyle/Series:	**Wagon XL**
Color:	**Blue**
Mileage:	**117,107 (Verified)**
Turn-in Mileage:	-
VIN:	**NM0GE9E76J1343608**
Work Order/ Stock Number:	**46492764**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G41-0022V**
Vehicle Grade :	**Grade 2.7**
Remarks:	-
Announcements:	• CRACKED WINDSHIELD
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2.5 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 215 / 55 R 16	Car Tire Size - LF 215 / 55 R 16	Car Tire Size - RF 215 / 55 R 16
Car Tire Size - LR 215 / 55 R 16	LF Tires - 8/32 inch	LR Tires - 6/32 inch
RF Tires - 8/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - SUREDRIVE
Tire Brand - Front Right - SUREDRIVE	Tire Brand - Rear Left - SUREDRIVE	Tire Brand - Rear Right - SUREDRIVE
Tire Model - RR - touring a/S	Tire Model - RF - touring a/S	Tire Model - LR - touring a/S
Tire Model - LF - touring a/S		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper Cover Upper	Misaligned	-	Repair Required
	Front Bumper	Misaligned	-	Repair Required
	Grille	Broken	-	Replacement Required
	Front Bumper Cover Upper	Chipped	-	10 Or More
	Left Head Lamp	Faded	-	Repair Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Head Lamp	Faded	-	Repair Required
	Right Front Fender	Chipped	-	10 Or More
	Left Front Fender	Chipped	-	3
	Right Rear Door	Multiple Scratches Heavy	-	5
	Right Qtr Panel	Chipped	-	3
	Lift Gate	Multiple Scratches Heavy	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Heavy Scratch	-	< 1/8 Inch
	Left Rear Door	Multiple Scratches Heavy	-	2
	Left Front Door	Heavy Scratch	-	1/2 To 1 Inch
	Left Front Fender	Dent(S) W/ Paint Dmg	-	1/8 To 1/2 Inch
	Right Front Wheel Cover	Curb Rash	-	> 12 Inches
	Left Front Wheel Cover	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Windshield	Cracked	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.