Approved CR

IAA Elkton
183 Zeitler Rd
Branch No 786
Elkton, MD 21921
(410) 695-4477
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2020 DODGE DURANGO**
Bodystyle/Series:	**Sport Utility Vehicle PURSUIT AWD**
Color:	**White**
Mileage:	**65,599 (Verified)**
Turn-in Mileage:	-
VIN:	**1C4RDJFG4LC261303**
Work Order/ Stock Number:	**46492884**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G626666W**
Vehicle Grade :	**Grade 3.1**
Remarks:	-
Announcements:	• Prior police
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**All Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment


Additional Equipment:

Car Tire Size - RR 265 / 60 R 18	Car Tire Size - RF 265 / 60 R 18	Car Tire Size - LF 265 / 60 R 18
Car Tire Size - LR 265 / 60 R 18	LF Tires - 10/32 inch	LR Tires - 10/32 inch
RF Tires - 8/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - RR - Wrangler Fortitude HT	Tire Model - RF - Wrangler Fortitude HT	Tire Model - LR - Wrangler Fortitude HT
Tire Model - LF - Wrangler Fortitude HT		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Left Drip Rail	Previous Repair	-	Acceptable
	Led Flashlight	Aftermarket	-	Acceptable
	Center Console	Aftermarket	-	Acceptable
	Warning Light - Electrical	On	-	Unacceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Keys	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	1/2 To 1 Inch
	Left Rear Door	Multiple Scratches Heavy	-	3
	Left Rear Wheel	Curb Rash	-	1 To 2 Inches
	Left Front Door	Multiple Scratches Heavy	-	2
	Left Front Fender	Chipped	-	2
	Left Front Seat Cushion	Torn	-	7 To 8 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Seat Molding	Loose	-	Repair Required
	Rear Bumper	Chipped	-	8
	Overall Vehicle	De-Identify	-	Removal Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.