Approved CR

IAA North Virginia
15 Le Way Drive
Branch No 723
Fredericksburg, VA 22406
(540) 373-7800/(540) 371-4123
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2019 FORD FUSION HYBRID**
Bodystyle/Series:	**4 Door Sedan SE**
Color:	**Blue**
Mileage:	**17,161 (Verified)**
Turn-in Mileage:	-
VIN:	**3FA6P0LU7KR149518**
Work Order/ Stock Number:	**46492999**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G120314V**
Vehicle Grade :	**Grade 3.8**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Continuously Variable Transmission**	A/C:	**Yes**
Engine:	**4-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 50 R 17	Car Tire Size - LR 225 / 50 R 17	Car Tire Size - RR 225 / 50 R 17
Car Tire Size - RF 225 / 50 R 17	LF Tires - 9/32 inch	LR Tires - 8/32 inch
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - FALKEN
Tire Brand - Front Right - FALKEN	Tire Brand - Rear Left - FALKEN	Tire Brand - Rear Right - FALKEN
Tire Model - RR - Ziex ZE950 A/S	Tire Model - RF - Ziex ZE950 A/S	Tire Model - LR - Ziex ZE950 A/S
Tire Model - LF - Ziex ZE950 A/S		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	2
	Right Rear Wheel	Curb Rash	-	1 To 2 Inches
	Left Rear Wheel	Curb Rash	-	1/2 To 1 Inch
	Left Front Wheel	Curb Rash	-	2 To 3 Inches
	Steering Wheel	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.