Approved CR

IAA Raleigh
60 Sadisco Road
Branch No 747
Clayton, NC 27520
(919) 553-6148/(919) 553-2857
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2017 CHEVROLET SILVERADO 2500HD**
Bodystyle/Series:	**Crew Cab WT**
Color:	**Green**
Mileage:	**80,480 (Verified)**
Turn-in Mileage:	-
VIN:	**1GC1KUEY6HF190075**
Work Order/ Stock Number:	**46486202**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G631373U**
Vehicle Grade :	**Grade 2.5**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment


Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Diesel**	Cruise Control:	**Yes**
Engine Size:	**6.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /-**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 75 R 17	Car Tire Size - LR 245 / 75 R 17	Car Tire Size - RR 245 / 75 R 17
Car Tire Size - RF 245 / 75 R 17	LF Tires - 12/32 inch	LR Tires - 8/32 inch
RF Tires - 11/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - GENERAL
Tire Brand - Front Right - GENERAL	Tire Brand - Rear Left - GENERAL	Tire Brand - Rear Right - GENERAL
Tire Model - RR - Grabber HD	Tire Model - RF - Grabber HD	Tire Model - LR - Grabber HD
Tire Model - LF - Grabber HD		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Heavy Scratch	-	1/2 To 1 Inch
	Right Front Wheel	Corrosion	-	9 To 10 Inches
	Right Bed Side	Multiple Dents/Paint Damage	-	3
	Right Rear Wheel	Corrosion	-	9 To 10 Inches
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Multiple Dents/Paint Damage	-	4
	Left Bed Side	Multiple Dents/Paint Damage	-	4
	Left Rear Wheel	Corrosion	-	7 To 8 Inches
	Left Front Wheel	Corrosion	-	2 To 3 Inches
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Left Tail Light	Cracked	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.