Approved
CR

IAA Honolulu
91-445A Komohana St
Branch No 114
Kapolei, HI 96707
(808) 682-2858/(808) 682-3988
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2017 CHEVROLET TAHOE**
Bodystyle/Series:	**Sport Utility Vehicle COMMERCIAL FLEET**
Color:	**White**
Mileage:	**60,767 (Verified)**
Turn-in Mileage:	-
VIN:	**1GNSKEEC4HR364004**
Work Order/ Stock Number:	**46367179**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G624100U**
Vehicle Grade :	**Grade 2.0**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**5.3 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Leather Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Memory**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Hydraulic Brakes**

Equipment


Additional Equipment:

Car Tire Size - RR 265 / 70 R 17	Car Tire Size - RF 265 / 70 R 17	Car Tire Size - LF 265 / 70 R 17
Car Tire Size - LR 265 / 70 R 17	LF Tires - 14/32 inch	LR Tires - 14/32 inch
RF Tires - 14/32 inch	RR Tires - 14/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - LF - Wrangler All-Terrain Adventure With Kevl	Tire Model - LR - Wrangler All-Terrain Adventure With Kevl	Tire Model - RF - Wrangler All-Terrain Adventure With Kevl
Tire Model - RR - Wrangler All-Terrain Adventure With Kevl		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required
	Front Bumper	Chipped	-	4
	Front Valance	Missing	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Multiple Scratches Heavy	-	2
	Right Front Wheel	Corrosion	-	5 To 6 Inches
	Right Front Door	Chipped	-	2
	Right Rear Wheel	Corrosion	-	3 To 4 Inches
	Rear Bumper	Multiple Scratches Heavy	-	4
	Hitchplate Cover	Missing	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Lift Gate	Chipped	-	5
	Corner Panel	Missing	-	Replacement Required
	Right Corner Panel	Missing	-	Replacement Required
	Left Rear Door	Chipped	-	2
	Left Rear Wheel	Corrosion	-	3 To 4 Inches
	Left Front Door	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Chipped	-	3
	Left Front Wheel	Corrosion	-	> 12 Inches
	Roof	Multiple Scratches Heavy	-	3
	Center Console	Missing	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.