



Approved CR

IAA Honolulu
91-445A Komohana St
Branch No 114
Kapolei, HI 96707
(808) 682-2858/(808) 682-3988
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018
CHEVROLET
EXPRESS
2500**

Bodystyle/Series: **Van LS**

Color: **Red**

Mileage: **65,066
(Verified)**

Turn-in Mileage: **-**

VIN: **1GAWGEFG1J1259771**

Work Order/
Stock Number: **46367095**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G433603U**

Vehicle Grade : **Grade 3.7**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Vinyl Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Memory	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Hydraulic Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 16	Car Tire Size - RF 245 / 75 R 16	Car Tire Size - LF 245 / 75 R 16
Car Tire Size - LR 245 / 75 R 16	LF Tires - 13/32 inch	LR Tires - 9/32 inch
RF Tires - 10/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - BRIDGESTONE
Tire Brand - Front Right - BRIDGESTONE	Tire Brand - Rear Left - BRIDGESTONE	Tire Brand - Rear Right - BRIDGESTONE
Tire Model - RR - VSB (V-Steel S-Block)	Tire Model - RF - VSB (V-Steel S-Block)	Tire Model - LR - VSB (V-Steel S-Block)
Tire Model - LF - VSB (V-Steel S-Block)		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Vehicle	De-Identify	-	Removal Required
	Left Rear Cargo Door	Multiple Scratches Heavy	-	2
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	7 To 8 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.