



Approved CR

IAA Portland/Gorham  
9 Moodys Dr  
Branch No 670  
Gorham, ME 04038  
(207) 839-2045/(207) 839-2701  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2010  
CHEVROLET  
MALIBU  
HYBRID**

Bodystyle/Series: **4 Door Sedan**

Color: **Tan**

Mileage: **63,167  
(Verified)**

Turn-in Mileage: **-**

VIN: **1G1ZF5EZ3AF109375**

Work Order/  
Stock Number: **46305550**

Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**

Client Stock #: **G10A0948**

Vehicle Grade : **Grade 3.4**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

### Equipment

|                        |                                            |                 |                          |
|------------------------|--------------------------------------------|-----------------|--------------------------|
| Transmission:          | <b>Automatic Transmission w/ Overdrive</b> | A/C:            | <b>No</b>                |
| Engine:                | <b>4-Cylinder Hybrid</b>                   | Cruise Control: | <b>Yes</b>               |
| Engine Size:           | <b>2.4 L</b>                               | Pwr Steering:   | <b>Yes</b>               |
| Roof:                  | <b>Hard Top</b>                            | Pwr Locks:      | <b>Yes</b>               |
| Radio:                 | <b>-</b>                                   | Pwr Windows     | <b>Yes</b>               |
| Interior - Type/Color: | <b>Cloth Interior /TAN</b>                 | Rear Defroster: | <b>Yes</b>               |
| Airbag:                | <b>Driver Side Air Bag</b>                 | Tilt Steering:  | <b>Yes</b>               |
| Seats:                 | <b>3rd</b>                                 | Drive Type:     | <b>Front Wheel Drive</b> |
| Seat Count:            | <b>-</b>                                   | Brakes:         | <b>Anti Lock Brakes</b>  |

## Equipment

### Additional Equipment:

Car Tire Size - RR 215 / 55 R 17

Car Tire Size - RF 215 / 55 R 17

Car Tire Size - LF 215 / 55 R 17

Car Tire Size - LR 215 / 55 R 17

LF Tires - 10/32 inch

LR Tires - 10/32 inch

RF Tires - 10/32 inch

RR Tires - 10/32 inch

Tire Brand - Front Left - VREDESTEIN

Tire Brand - Front Right - VREDESTEIN

Tire Brand - Rear Left - VREDESTEIN

Tire Brand - Rear Right - VREDESTEIN

Tire Model - LF - Hypertrac

Tire Model - LR - Hypertrac

Tire Model - RF - Hypertrac

Tire Model - RR - Hypertrac

## Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity     |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|--------------|
|    | Warning - Tire Pressure | On         | -      | Unacceptable |
|   | Odometer                | Photo Only | -      | -            |
|  | Extra Photo 1           | Photo Only | -      | -            |
|  | Photo - Dash            | Photo Only | -      | -            |
|  | Right Rear Bumper/Cover | Photo Only | -      | -            |
|  | Left Rear Bumper/Cover  | Photo Only | -      | -            |
|  | Left Front Fender       | Photo Only | -      | -            |

### Non Chargeable Damages

| Photo                                                                               | Item                   | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|------------------------|------------|--------|----------|
|    | Right Front Fender     | Photo Only | -      | -        |
|    | Rear Bumper            | Photo Only | -      | -        |
|    | Instrument Panel       | Photo Only | -      | -        |
|    | Left Side Panel        | Photo Only | -      | -        |
|    | Right Side Panel       | Photo Only | -      | -        |
|   | Front Cover Center     | Photo Only | -      | -        |
|  | Keys                   | Photo Only | -      | -        |
|  | Engine                 | Photo Only | -      | -        |
|  | Photo - Vin/Id Sticker | Photo Only | -      | -        |
|  | Rear Seats             | Photo Only | -      | -        |

| Chargeable Damages                                                                  |                    |                      |        |                 |
|-------------------------------------------------------------------------------------|--------------------|----------------------|--------|-----------------|
| Photo                                                                               | Item               | Damage               | Action | Severity        |
|    | Right Rear Wheel   | Curb Rash            | -      | > 12 Inches     |
|    | Right Front Door   | Heavy Scratch        | -      | 1/2 To 1 Inch   |
|    | Right Front Wheel  | Curb Rash            | -      | > 12 Inches     |
|   | Right Front Fender | Dent(S) W/ Paint Dmg | -      | 4 To 5 Inches   |
|  | Front Bumper       | Chipped              | -      | 1               |
|  | Left Head Lamp     | Faded                | -      | Repair Required |

### Chargeable Damages

| Photo                                                                               | Item              | Damage        | Action | Severity        |
|-------------------------------------------------------------------------------------|-------------------|---------------|--------|-----------------|
|    | Right Head Lamp   | Faded         | -      | Repair Required |
|    | Left Front Door   | Heavy Scratch | -      | 1/2 To 1 Inch   |
|    | Rear Bumper       | Chipped       | -      | 1               |
|   | Left Front Fender | Chipped       | -      | 3               |
|  | Left Front Wheel  | Curb Rash     | -      | > 12 Inches     |
|  | Left Rear Wheel   | Curb Rash     | -      | > 12 Inches     |

| Chargeable Damages                                                                |          |         |        |             |
|-----------------------------------------------------------------------------------|----------|---------|--------|-------------|
| Photo                                                                             | Item     | Damage  | Action | Severity    |
|  | Deck Lid | Scuffed | -      | > 12 Inches |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.